STATE OF NEW MEXICO	
ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION P. O. BOX 2088	Form C-103 - Revised 10-1-73
SANTA FE. SANTA FE. NEW MEXICO 87501	Sa. Indicate Type of Lease State X Fee
OPERATOR	5. State Oll & Gas Lease No. LG 3345
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FOR PROPOSALS TO DRILL OR TO DECEMENT OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL AS GAS OTHER-	8. Farm or Lease Name
Yates Petroleum Corporation	Hoover ADR State
105 South 4th St., Artesia, NM 88210	6
4. Location of Well UNIT LETTER	10. Field and Pool, or Wildcat Sanmal-Queen
THE West LINE, SECTION 1 TOWNSHIP 175 RANGE 33E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 4148.7' GR	12. County Lea
The check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO: SUBSEQUENT	ner Data REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORR TEMPORARILY ABANDON PULL OR ALTER CASING COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JQB X OTHER	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	
TEMPORARILY ABANDON PULL OR ALTER CASING COMMENCE DRILLING OPHS. COMMENCE DRILLING OPHS. CASING TEST AND CEMENT JQB OTHER	PLUG AND ABANDONMENT
TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS OTHER	PLUG AND ABANDONMENT
TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS OTHER OTHER II. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. Spudded 12-1/4" hole at 11:30 AM 6-22-87. Drilled to TD 1415'. Stuck drill pipe and collars. Set cement plug 715' and cemented with 220 sacks Class "H" with 2% 3:30 AM 6-25-87. WOC.	PLUG AND ABANDONMENT
TEMPORABILY AGANDON PULL OR ALTER CASING CHANCE PLANS CHANCE PLANS COMMENCE DEFILING OPENS. OTHER OTHER II. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. Spudded 12-1/4" hole at 11:30 AM 6-22-87. Drilled to TD 1415'. Stuck drill pipe and collars. Set cement plug 715' and cemented with 220 sacks Class "H" with 2% 3:30 AM 6-25-87. WOC. Reached TD to run casing 10:30 AM 6-28-87. Ran 36 joitns 8-5/8" J-55 24# casing set 1535'. I-Texas Pattern not set 1535, insert float set 1493'. Cemented with 575 sacks Pacesett with 1/4# celloseal (yield 2.01, weight 12.4). Tailed in with 200 with 2% CaCl2 (yield 1.32, weight 14.8). PD 4:30 PM 6-28-87. Bump si, released pressure and float held okay. Cement circulated 100 WOC.	PLUG AND ABANDONMENT

I hereby certify th	hat the information above is true and compl	ete to the best of my knowledge and belief,	
+topinga	inta Doublett	Production Supervisor	6/29/87
/ ////////////////////////////////////	Original signed by		
OVED BY	Post Kautz	TITLE	JUL 2 1981

•



ан 1917 - 1917 - 1917 - 1917 - 1917 - 1917 - 1917 - 1917 - 1917 - 1917 - 1917 - 1917 - 1917 - 1917 - 1917 - 1917