## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I

Je GWW

OIL CONSERVATION DIVISION WELL API NO.

P.O. Box 1980, Hobbs, NM 88240  310 Old Santa Fe Trail, Room 206  DISTRICT II  P.O. Drawer DD, Artesia, NM 88210  Santa Fe, New Mexico 87503	30-025-30049
	5. Indicate Type of Lease STATE FEE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
	21079 (VA-682)
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL	STATE 7
2 Name of Operator	8. Well No.
AVRA OIL COMPANY  3. Address of Operator	9. Pool name or Wildcat
P.O. BOX 3193, MIDLAND, TX 79702	Kemaitz Cisco
4. Well Location  Unit Letter I: 1980 Feet From The SOUTH Line and 990	Feet From The <u>EAST</u> Line
34F	NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
4141.1	Penort or Other Data
Check Appropriate Box to Indicate Nature of Notice, F	BSEQUENT REPORT OF:
NOTICE OF INTENTION TO:	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIN	IGOPNS. PLUG AND ABANDONNETT
PULL OR ALTER CASING CASING TEST AND C	EMENT JOB
OTHER: OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, in work) SEE RULE 1103.	cluding estimated date of starting any proposed
10-27-00 LAID DOWN RODS 10-28-00 CIRCULATED HOLE WITH 300 BBLS OF 36 VIS 10-30-00 PULLED TUBING 10-31-00 SET CIBP @ 29500' PLUS TWO SACKS OF CEMENT 11-1-00 RUN FREE POINT, NO CASING TO RECOVER LETTER OF COMPANY AND CASING TO RECOVER LETTER OF COM	NT EFT ALL 5 1/2 CASING IN HOLE T 2ND PLUG @ 4535-4271(TAGGEI ATD PLUG. 25 SACKS @ 500-375
SET 1 ST PLUGS, 25 sacks @6500-6126, 3E SET 3RD PLUG, 25 sacks @1400-1028, SET (TAGGED), SET 5TH PLUG, 10 sacks @30'- S EMPTIED CELLAR AND WELDED A PLATE AND D	OKFACE ALL CHIEF & CHIEKT
SET 3RD PLUG, 25 sacks @1400-1028, SET (TAGGED), SET 5TH PLUG, 10 sacks @30'- S  EMPTIED CELLAR AND WELDED A PLATE AND D  Approved as to plugging of the Well Bore.  Liability under bond is retained until surface restoration is completed.	RY HOLE MARKER  Approved as to plugging of the Well Bore.  Liability under bond is retained until
SET 3RD PLUG, 25 sacks @1400-1028, SET (TAGGED), SET 5TH PLUG, 10 sacks @30'- S  11-3-00 EMPTIED CELLAR AND WELDED A PLATE AND D  Approved as to plugging of the Well Bore.  Liability under bond is retained until surface restoration is completed.	Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.
SET 3RD PLUG, 25 sacks @1400-1028, SET  (TAGGED), SET 5TH PLUG, 10 sacks @30'- S  11-3-00 EMPTIED CELLAR AND WELDED A PLATE AND D  Approved as to plugging of the Well Bore.  Liability under bond is retained until surface restoration is completed.  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SKONATURE  TILE PRESIDENT	Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.  DATE  12/04/00  DATE  215.682-4866
SET 3RD PLUG, 25 sacks @1400-1028, SET (TAGGED), SET 5TH PLUG, 10 sacks @30'- S  11-3-00 EMPTIED CELLAR AND WELDED A PLATE AND D  Approved as to plugging of the Well Bore.  Liability under bond is retained until surface restoration is completed.  Thereby certify that the information above is true and complete to the best of my knowledge and belief.	Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.
SET 3RD PLUG, 25 sacks @1400-1028, SET  (TAGGED), SET 5TH PLUG, 10 sacks @30'- S  EMPTIED CELLAR AND WELDED A PLATE AND D  Approved as to plugging of the Well Bore.  Liability under bond is retained until surface restoration is completed.  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SKONATURE  TILE PRESIDENT	Approved as to plugging of the Well Bore.  Liability under bond is retained until surface restoration is completed.  The part 12/04/00  The part 12/04/00