

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Exploration & Production Co.	8. Farm or Lease Name Anderson "A"
3. Address of Operator P. O. Box 1861, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER M 3300 FEET FROM THE South LINE AND 710 FEET FROM THE West LINE, SECTION 6 TOWNSHIP 16-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Northeast Lovington - Pennsylvanian
15. Elevation (Show whether DF, RT, GR, etc.) 3866.4'GR	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-26-88 Spudded @ 4:00 P.M., 17-1/2" hole, R&C 11 jts, 13-3/8" csg, K&J, 8 rd & Butt, CS @ 416'. Western cmt'd w/450 sxs "C", circ'd 109 sxs, WOC 11-1/2 hrs.  
2-1-88 R&C 106 jts, 8-5/8" csg, 32#, K-STC, CS @ 4300', FC 4216'. Western cmt'd w/1250 sxs lite, followed by 200 sxs "C", FP 1450-1750, circ'd 222 sxs, floats held, WOC 14 hrs.  
2-21-88 Reached TD 11,725'.  
2-24-88 R&C 278 jts, 5-1/2", 17#, K-55, N-80 & LTC & BTC, CS 11,732', FC 11,685', DV Tool 8809'. Cmt'd 1st stage w/500 sxs "H", 50-50 poz, did not bump plug. FP 1500, floats held O.K. opened DV tool, circ'd 4 hrs, no cmt rec'd off DV tool. Cmt'd 2nd stage w/950 sxs pacesetter lite, tailed in with 150 sxs "C", FP 2300#, closed DV tool w/3800#, full circ, did not rec cmt. Ran temperature survey, TOC 4880'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Maria I. Perez TITLE Accounting Associate DATE 7-8-88

ORIGINAL SIGNED BY JOHN E. SYTON  
DISTRICT SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: