Submit 3 Copies State of New Mexico to Appropriate nergy, Minr District Office s and Natural Resource			Form Revise	C-103 ed 1-1-89		
DISTRICT I P.O. Box 1980, Hobbs, NM 88240OIL CONSERVATION DIVISION 2040 Pacheco St. Santa Fe, NM 87505DISTRICT II P.O. Drawer DD, Artesia, NM 88210Santa Fe, NM 87505		WELL API NO. 30-025-30349				
		5. Indicate Type of Lease STATE FEE FEE				
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Ga	as Lease No.			
SUNDRY NOTICES AND REPORTS ON W	VELLS					
(DO NOT USE THIS FORM FOR PORPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		7. Lease Name or Unit Agreement Name				
1. Type of Well: OL X GAS WELL OTHER		Berry Hobbs				
2. Name of Operator		8. Well No.	// 1			
Bonneville Fuels Corporation	#1					
3. Address of Operator	9. Pool name or Wildcat North Shoe Bar - Wolfcamp					
1700 Broadway, Suite 1150, Denver, CO 80290		North Shoe Dar	- woncamp			
4. Well Location Unit Letter <u>A</u> <u>700</u> Feet From The <u>North</u>	Line and	980	Feet From The	East 1	Line	
Section 17 Townshi 16S Range 36E		NMPM	Lea	Cou	inty	
10. Elevation (Show wheth 3926 GR	3941 KB					
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data						
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:					
	REMEDIAL WORK		ALTERING CASIN	ıg		
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS.					
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB					
OTHER:	OTHER: <u>Perf. Lwr. Wolfcamp/Abandon under Ret./Resume</u> orig					

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date, including estimated date of starting any proposed work) SEE RULE 1103.

7/25/00 MIRU PU. POOH & LD Pump & rods. POOH & inspect & LD bad tubing. RU foam unit & RIH w/ 3-7/8" bit & deepen PBD in casing f/ 10,734' to 10,754'. POOH & LD Bit. RIH w/ hydrotest & set 5 1/2" packer @ 10,616'. Install tree & perforated Wolfcamp Blue Zone 10,740'-10,750' with 4 jspf .30" holes, total of 40 holes. Acidized with 500 gal 15% HCL + additives. Swabbed well recovered 100% water to 175 BW over load. Rig released 8/03/00. Evaluate options.

9/18/00 MIRU PU. ND Tree & POOH w/ 5 1/2" packer. PU & RIH w/ 5 1/2" HOWCO EZSV cement retainer & set @ 10,601'. RIH & set 5 1/2" packer @ 10,291'. Re-acidize original upper wolfcamp perfs 10,357-10,375' with 1000 gal 15% HCL @ 30 PSIG & displaced w/ 70 bbls 4% KCL water. Swabbed well to clean up. Unseat packer & POOH & LD packer. Ran 2 7/8" tubing with end of assembly @ 10,476'. Ran pump & rods and returned well to production 9/26/00.

I hereby certify that the information above is such above the dest of m	v knowledge and belief.		
A landamal	TITLE Operations Manager SENM	DATE	10/17/00
TYPE OR PRINT NAME R. A Schwering, P.E.		HONE NO.	303 863-1555 x 213
(This space for State Use)	ORIGINAL CONTRACTOR		
APPROVED BY		DATE	
CONDITIONS OF APPROVAL, IF ANY:			$\mathbf{t} = \mathbf{t}$

