

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Foran Oil Company	8. Farm or Lease Name Rouse '5'
3. Address of Operator 8340 Meadow Road, Suite 158, Dallas, TX 75231	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> <u>3950</u> FEET FROM THE <u>North</u> LINE AND <u>1550</u> FEET FROM THE <u>West</u> LINE, SECTION <u>5</u> TOWNSHIP <u>16S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3941' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set 35 sx plug @ 12,070', set 45 sx plug @ 11,535', set 50 sx plug @ 9,870', set 50 sx plug @ 8,250', set 45 sx plug @ 6,250', set 50 sx plug @ 4752', set 35 sx plug @ 2,010' and 35 sx plug @ 425'.

Set 8 100' Plugs as required by the New Mexico Oil Conservation Division.

See Attachment for detail of plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christy Wilson TITLE Production Clerk DATE June 14, 1988

APPROVED BY R A Padilla TITLE OIL & GAS INSPECTOR DATE JAN 03 1989

CONDITIONS OF APPROVAL, IF ANY:

