STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

40. 87 (0-168 ACCEIVED	T	
DISTRIBUTION		
BANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR	i	

CONDITIONS OF APPROVAL, IF ANY:

OIL CONSERVATION DIVISION

DISTRI				Form C-103		
SANTA FE	SANTA FE, NEW MEXICO 87501					
FILE				Sa. Indicate Type of Lease		
U.S.G.S.			•	State Foe X		
LAND OFF	ICE					
OPERATOR		}		5. State Off & Gus Lease No.		
	SUNDR	Y NOTICES AND REPORTS ON	IWFLLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)						
T1.				7. Unit Agreement Name		
01L	GAS WELL	OTHER-		}		
2. Name of Operate		07827		8. Form or Lease Name		
	Rouse '5'					
Foran Oi	9. Well No.					
3. Address of Open						
		uite 158, Dallas, TX	/5231	1		
4. Location of Wel				10. Field and Pool, or Wildcat		
UMIT 57758	K 39	50 FEET FROM THE North	LINE AND 1550 FEET FAC	Wildcat		
Wes	t.	5 TOWNSHIP 16S	BANGE 36E			
THE	LINE, SECTIO	TOWNSHIP	MANGENEPS			
TTTTTTTT	mm	15. Elevation (Show whether	DF. RT. GR. etc.)	12. County		
			51, K7, 5K, 5K1,			
	777777777777777777777777777777777777777	3941' GL		Lea ()		
16.	Check	Appropriate Box To Indicate N	Nature of Notice, Report or O	ther Data		
		TENTION TO:		T REPORT OF:		
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					
		PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING		
PERFORM REMEDIA	L WORK	PEGG AND ABANDON	一	<u>—</u>		
TEMPORARILY ABAR	HDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT		
PULL OR ALTER CA	31HG	CHANGE PLANS	CASING TEST AND CEMENT JOB	X		
			OTHER Spud			
OTHER						
			ails and aire partiaget datas includin	a estimated date of starting any proposes		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.						
•						
Spudded	subject wel	1 @ 8:30 AM MDT on 4	/22/88.			
4/27/88 Ran 13 jnts K-55 ST&C 61# 13-3/8" csg to 394'. Cmtd w/500 sx Cl "H"						
neat cmt. Circ cmt to surface & 65 sx to pit. WOC 18 hrs. Installe						
13-3/8" X 13-5/8" casinghead.						
	13 3/0 11	13 3/0 casingneau				
F /04/00	Dan 114 3+	s 8-5/8" 32# J-55 &	V-55 cca Sot 0 470	12' Cm+d w/250 sy		
5/04/88	Kan 114)	te w/5# salt, follow	R-33 CSg. Sec 8 476	nest Pumped plug		
	western 11	te W/5# Sait, IOIIOW	red by 200 sx Ci n	Telegrad programs		
	@ 11·45 am	Tested csg to 180	U# for 10 min - Ok.	Refeased pressure,		
			it 360'. NU & tested	l pipe & BOP to 1000#		
	for 30 min	. WOC 18 hrs.				
				·		
18. I hereby certify	that the information	above is true and complete to the best	of my knowledge and belief.			
/ 11						
	Unit	11/1/s/som	oduction Clerk	OATE 7/14/88		
SICHED	WWW.	July Hitte PI	oduction ciers	_ UATE //14/00		
C	HGINAI FICKTOR	34 34 Days				
• • • • • • • • • • • • • • • • • • • •	वरणान्यास्त्रास्य । जनसम्बद्धाः हिन्तुः हिन्तुः । जनसम्बद्धाः । जनसम्बद्धाः ।	A SPACE SEALON				