

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-025-30370

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

N.H. 5A State

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
Devon SFS Operating, Inc.

8. Well No. 1

3. Address of Operator  
20 North Broadway, Ste. 1500, Oklahoma City, OK 73102

9. Pool name or Wildcat  
N. Hume Wolfcamp

4. Well Location  
Unit Letter K : 4620 Feet From The South Line and 1980 Feet From The West Line  
Section 5 Township 16-S Range 34-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
4151.3' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/20/02 Ran 4-1/2" bit on tbg and tag up solid @ 9020'. POOH w/ bit, set 5-1/2" CIBP @ 9010'.  
Cap w/ 35' of cmt., tag TOC @ 8973'.

2/20/02 Mix and circulate hole w/ 10# mud.

2/20/02 Spot 25 sx "C" cmt. @ 7305' to 7040'.

2/22/02 Spot 25 sx "C" cmt. from 4516' to 4251', WOC & tag TOC @ 4273'.

2/22/02 Cut off 5-1/2" csg. @ 1800'.

2/22/02 Spot 35 sx "C" cmt. from 1850' to 1680', WOC and tag @ 1673'.

2/23/02 Spot 35 sx "C" cmt. from 495' to 365', WOC and tag @ 358'.

2/23/02 Spot 15 sx "C" cmt. from 60' to surface.

2/25/02 Cut off wellhead and install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE Agent DATE 2/27/02

TYPE OR PRINT NAME Roger Massey TELEPHONE NO. (915) 530-0907

(This space for State Use)

APPROVED BY Billy E. Prueh TITLE COMPLIANCE OFFICER DATE MAY 20 2002

CONDITIONS OF APPROVAL, IF ANY: