

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30529
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Stansell
8. Well No. 1
9. Pool name or Wildcat Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole
2. Name of Operator Union Oil Company of California
3. Address of Operator P. O. Box 671 - Midland, Texas 79702
4. Well Location Unit Letter <u>B</u> : <u>660</u> Feet From The <u>north</u> Line and <u>1980</u> Feet From The <u>east</u> Line

Section <u>13</u>	Township <u>15-S</u>	Range <u>34-E</u>	NMPM	Lea	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4052.1' GR					

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/27-MIRU Pool Well service. RIH w/2 3/8" tbg to CIBP @ 10,650'. Disp hole w/10 ppg mud. FU & spot 50 sxs Cl "C" amt from 10,650-10,200'. Spot 25 sxs Cl "C" amt from 8000-7747'. Spot 25 sxs Cl "C" amt from 5770-5518'. Spot 25 sxs Cl "C" amt from 4700-4448'. POCH, incorp.

11/28-Finish POCH w/2 3/8" tbg. ND BOP. Weld on 5 1/2" pull nipple. Cut 5 1/2" csg. @ 2681'. Worked pipe for 1 hr. & could not work free. Cut 5 1/2" csg @ 2555'. Lay down 5 1/2" csg.

11-29-RIH w/2 3/8" tbg open ended to 2745'. Spot 50 sxs Cl "C" amt w/2% CaCl from 2745-2490'. FU & WOC 4 hrs. RIH & tag amt. @ 2490'. FU & spot 25 sxs Cl "C" amt from 1850-1775'. FU & spot 25 sxs Cl "C" from 447-372'. FU & spot 10 sxs Cl "C" amt from 30' to surf. Cut off 9 5/8" & 13 3/8" csg. Weld on P&A plate & install dry hole marker. RDU. Clean location. Well P&A 11-29-89.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bobby Bryan TITLE Drilling Superintendent DATE 12-5-89

TYPE OR PRINT NAME Bobby Bryan

TELEPHONE NO (915) 682-9731

(This space for State Use)

APPROVED BY: Franklin R. Smith TITLE OIL & GAS INSPECTOR DATE MAR 16 1990

CONDITIONS OF APPROVAL, IF ANY: