

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. <u>30-025-30529</u>
5. Indicate Type of Lease: STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <u>Stansell</u>
8. Well No. <u>1</u>
9. Pool name or Wildcat <u>Wildcat</u>

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER <u>Dry Hole</u>	2. Name of Operator <u>Union Oil Company of California</u>
3. Address of Operator <u>P.O. Box 671 - Midland, Texas 79702</u>	4. Well Location Unit Letter <u>B</u> : <u>660</u> Feet From The <u>north</u> Line and <u>1980</u> Feet From The <u>east</u> Line Section <u>13</u> Township <u>15-S</u> Range <u>34-E</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>4052.1' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS.: ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

See attached

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jeffery J. Tokarsky TITLE Drilling Engineer DATE 5-26-89
TYPE OR PRINT NAME Jeffery J. Tokarsky TELEPHONE NO. (915) 682-9731

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 30 1989

PLUGGING PROCEDURE FOR STANSELL WELL NO. 1 - LEA COUNTY, NEW MEXICO

1. RIH to CIBP @ 10,650'. Disp hole w/10# brine w/25#/bbl salt gel.
2. Dump 50 sxs "C" on CIBP from 10,200' to 10,650'. PLUG NO. 6.
3. PUH. Spot 25 sxs "C" from 7747' to 8000'. PLUG NO. 7.
4. PUH. Spot 25 sxs "C" from 5518' to 5770'. PLUG NO. 8.
5. PUH. Spot 25 sxs "C" from 4448' to 4700'. PLUG NO. 9.
6. POH. Free point csg. RIH w/csg cutter and cut csg @ $\pm$ 2800'.
LD csg.
7. RIH. Spot 30 sxs "C" 50' above and 50' below cutoff point. PLUG NO. 10.
8. PUH. Spot 25 sxs "C" from 1775' to 1850'. PLUG NO. 11.
9. PUH. Spot 25 sxs "C" from 372' to 447'. PLUG NO. 12.
10. PUH. Spot 10 sxs "C" from 3' BGL to 30' BGL. PLUG NO. 13.
11. Dig out cellar. Cut csqs 3' BGL. Weld or P&A plate and dry hole marker.
Clean up location.

WORK TO BE DONE

S. Jansell #1

PRESENT CONDITION

PLUG NO. 13 10 SXS
from surf to 30' BGL

PLUG NO. 12 25 SXS
from 372 to 447

PLUG NO. 11 25 SXS
from 1775 to 1850

PLUG NO. 10 30 SXS
cut 5 1/2' @ ± 2800
cut plug 50' in &
50' out

PLUG NO. 9 25 SXS
from 4448 to 4700

PLUG NO. 8 25 SXS
from 5518 to 5770

PLUG NO. 7 25 SXS
from 7747 to 8000

PLUG NO. 6 50 SXS
from 10200 to 10650

Note:

- 1) KB is 22' AGL
- 2) hole is to be disp
w/ 10# brine with
25 lb/bbl salt gel

13 3/8 40 H-40 @ 447.
CIRC CNT.

TOC @ 2800
by temp SURV.

9 5/8 36 S-804 K-55
@ 4700. CIRC CNT.

cibp @ 10650

± 10707-14, 20-26 (28) (CISCO)

± 10750 PLUG NO. 5
± 10764-808 (89) sqzd (CISCO)

cibp @ 11620 w/ 25' cut PLUG NO. 4
± 11673-82 (37) (Canyon)

cibp @ 12800 w/ 35' cut PLUG NO. 3
± 12844-47, 64-67, 76-78, 85-90
± 909-914 (77) (Upper Chester)

cibp @ 13050 w/ 35' cut PLUG NO. 2
± 13078-88, 118-23, 158-63 (83) (Chester)

± 14024 PLUG NO. 1
± 14144-52, 66-76, 79-92 (127) sqzd
± 14178-85 (29) sqzd (Devonian)

5 1/2 20 & 17 N-80 @ 14250.
TOC @ 2800 by temp SURV.

RECEIVED

MAY 30 1989

OCD
HOBBS OFFICE