

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING
OFFICE FOR NUMBER
OF COPIES REQUIRED
(Other instructions on re-
verse side)

BH Roswell District
Modified Form No.
NMXO-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. LC-058514	
2. NAME OF OPERATOR Marbob Energy Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Drawer 217, Artesia, NM 88210		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 330 FNL 330 FEL unit A		8. FARM OR LEASE NAME Pearsall BX	
14. PERMIT NO. 30-025-30696		9. WELL NO. 4	
15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3958' GR		10. FIELD AND POOL, OR WILDCAT Pearsall Queen Maljamar Grbg SA	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR ARDA Sec. 34-T17S-R32E	
		12. COUNTY OR PARISH Lea	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6/28/90 RU, pulled rods & tbq, perfed csg @ 3448-56', 3464-72', RIH w/pkr & plug, acd perfs 3448-72' w/500 gals. 15% NE ac, swb dry.

6/29/90 POH w/pkr, frac perfs 3448-72' w/20,000 gals. gel wtr and 210 sx 20/40 sand & 150 sx 12/20 sand.

7/1/90 Wash sand off plug, POH, RIH w/tbg & rods, landed tbq @ 4425', tbq anchor @ 3184', put well back on pump. Pmpd 17 BO 6 BW.

RECEIVED

AUG 9 10 35 AM '90

CARD AREA

ACCEPTED FOR RE-ENTRY

AB

AUG 16 1990

AUG 7 11 37 AM '90

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED Rhonda Nelson

TITLE Production Clerk

DATE 8/6/90

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side