Submit 3 Copies
t. Appropriate
District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

| P.O. Box 1980, Hobbs, NM 88240 P.O. Box 1980, Hobbs, NM 88240 P.O. Bo  |   | WELL API NO.  |
|--|---|---|
| DISTRICT II Santa Fe New Me  |   | 30-025-30769  |
| P.O. Drawer DD, Artesia, NM 88210  DISTRICT III  |   | 5. Indicate Type of Lease STATE XX FEE  |
| 1000 Rio Brazos Rd., Aztec, NM 87410   |   | 6. State Oil & Gas Lease No.<br>VB 0015   |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  |   |   |
|  |   | 7. Lease Name or Unit Agreement Name  |
| 1. Type of Well: Oil GAS WELL XX WELL COTHER   |   | Daisy AFS State   |
| 2. Name of Operator YATES PETROLEUM CORPORATION  |   | 8. Well No.   |
| 3. Address of Operator   | <del> </del>  | 1 No. Part No.  |
| 105 South 4th St., Artesia, NM 88210   |   | 9. Pool name or Wildcat   |
| 4. Well Location   |   | NE Eidson Missisippian  |
| Unit Letter G : 2310 Feet From The North   | Line and 1650   | Feet From The <u>East</u> Line  |
| Section 3 Township 16S   | Range 35E 1<br>ether DF, RKB, RT, GR, etc.)   | NMPM Lea County   |
| 10. Elevation (3.how wh<br>4007.5  | •   |   |
| 11. Check Appropriate Box to Indic   |   | mort or Other Date  |
| NOTICE OF INTENTION TO:  |   | SEQUENT REPORT OF:  |
|  | <b>一 一</b>  |   |
|  | REMEDIAL WORK   | ALTERING CASING   |
| TEMPORARILY ABANDON CHANGE PLANS [   | COMMENCE DRILLING   |   |
| PULL OR ALTER CASING   | CASING TEST AND CEI   | MENT JOB XX   |
| OTHER:   | OTHER: Set Surf   | ace & Intermediate Casing X   |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent detawork) SEE RULE 1103.  | ils, and give pertinent dates, include  | ing estimated date of starting any proposed   |
| 5-9-90. Ran 10 joints 13-3/8" 54.5# J-55 1 Insert float set 382'. Cemented w/450 sx 6 PD 4:30 PM 5-9-90. Bumped plug to 500 psi Drilled out 5:45 AM 5-10-90. WOC 12 hrs, 10 on flow nipple. Resumed drilling. 5-15-90. Ran 105 joints 8-5/8" 32# ST&C cas ST&C, casing set 4582'. Guide shoe set 458 Pacesetter Lite C w/6# salt + 1/4# Celloses Class C (yield 1.32, wt 14.8). PD 9:30 AM Circualted 75 sacks. WOC. NU and tested to 5-16-90. WOC 12 hrs and 45 minutes. Reduce | Class "C" + 2% CaCl, float held. Circ 15 mins. Reduced hasing as follows: 32', float collar sal (yield 2.02, wt 5-16-90. Bumped pro 1000 psi for 30 cm. | 2 (Yield 1.32, wt 14.8).  Sulated 45 sacks. WOC.  Sole to 11". Cut off and weld  14 jts H-80 ST&C 91 jts J-55  et 4538'. Cemented w/1600 sx  12.4). Tailed in w/200 sx  lug to 2000 psi, held okay. |
| I hereby certify that the information above is true and complete to the best of my knowledge   | and belief.   |   |
| $d \cdot f \cdot A$  | mme Production Sup  | pervisor 6-6-90   |
| TYPEOR PRINT NAME Juanita Goodlett   |   | ТЕ <b>L</b> ЕРНОNE NO. 505/748—147  |
| (This space for State Use)   |   |   |
| ORIGINAL SIGNED BY JERRY SEXTON  |   |   |
| DISTRICT I SUPPRIVISOR   | TITLE   | JUN 08 1990   |
| CONSTRAIN OF A DEPOSITATION AND  |   | DATE  |