

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instruction on reverse side)

Budget Bureau No. 1004-0115
Expires August 31, 1985

LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

| | | | | | | | | |
|--|---|---|--|------------------|---|---|----------------------------|----------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 2. NAME OF OPERATOR OXY USA Inc. | 3. ADDRESS OF OPERATOR P.O. Box 50250 Midland, TX. 79710 | 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980 FNL 1980 FWL Sec 31 (SENW) T17S R32E Unit F | 5. WELL NO. 1 | 6. FIELD AND POOL, OR WILDCAT Maljamar, GBSA | 7. SEC., T., R., M., OR BLM. AND SUBST. OR AREA Sec 31 T17S R32E | 8. COUNTY OR PARISH Lea | 9. STATE NM |
| 10. PERMIT NO. 300253079400S01 | 11. ELEVATIONS (Show whether OF, RT, OR, etc.) 3862.6' | 12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data | | | | | | |

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

FRACTURE TREAT

ABANDON OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD-4250' PBTD-3981' Perfs-3951'-3975'. The well was Plug & Abandon in the following manner:

POOH w/ tbg & pkr, RU wireline, RIH w/ a 5-1/2" CIBP and set @ 3900'. POOH, RD wireline, RIH w/tbg & dump 4 sx (50') C1 C cem on top of CIBP from 3900'-3850'. POOH to 3850', circ hole w/ 9.5# mud laden fluid, test csg & CIBP to 1000#, held OK. POOH to 3750', set 10 sx (100') cem 3750'-3650'. POOH to 3287', set 10 sx (100') cem 3287'-3187'. POOH to 2136', set 10 sx (100') cem from 2136'-2036'. POOH to 1085', set 34 sx (325') cem from 1085'-750'. POOH, SION. RIH w/ tbg, tag plug @ 806', spot 20 sx (200') cem from 806'-606'. POOH, SION. RIH w/ tbg, tag plug @ 604', POOH to 60', set 6 sx (60') cem from 60'-surface. POOH, NDBOP, cutoff wellhead, install dry hole marker, RDPU, cutoff anchors.

Well P&A'd 4/26/90. Job was witnessed by Jack Johnson w/ BLM.

18. I hereby certify that the foregoing is true and correct

SIGNED D. Charles Brown

TITLE Supervisor - Prod. Rpt.

DATE 5/14/90

(This space for Federal or State office use)

(Prepared by David Stewart)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

Approved as to accuracy of well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.