

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30879
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Julia Culp (Com)
8. Well No.	2
9. Pool name or Wildcat	Big Dog Mississippian
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3954.9' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Bridge Oil Company, L.P.
3. Address of Operator 12404 Park Central Drive, Suite 400, Dallas, Texas 75251	4. Well Location Unit Letter <u>H</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>34</u> Township <u>15S</u> Range <u>35E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3954.9' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU service unit to plug and abandon well as follows: Set CIBP @ 11,650' w/ 35' cement plug on top of CIBP (uppermost perfs @ 11,710'). Cut and pull 5-1/2" production casing @ +/- 9,000'. Set 100' cement plug from 8,950'-9,050', tag plug. Set 100' cement plug from 6,190'-6,290' (top of Glorietta). Set 100' cement plug from 4,738'-4,838', tag plug (8-5/8" casing shoe @ 4,788'). Set 100' cement plug from 1,800'-1,900' (top of salt). Set 10 sack cement surface plug. Hole will be filled with 10# salt gel between plugs. Surface location will be cleaned and restored as necessary. Verbal approval of this proposal was obtained from Eddie Seay on January 23, 1991.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Michael Warren TITLE Regulatory Analyst DATE 1-23-91
TYPE OR PRINT NAME J. Michael Warren TELEPHONE NO. (214) 788-3363

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY Jerry Sexton TITLE DATE JAN 29 1991

CONDITIONS OF APPROVAL, IF ANY: