Submit 1 Corries to Appropriate
District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICTJ P.O. Box 1980, Hobbs, NM 88240

OII.	CONSER	VATION	DIVISION
ULL.	COLIDEN	IIII	22,22

P.O. Box 2088

WELL API NO.	
30-025-31109	
5. Indicate Type of Lease STATE	FEE 🗌
6. State Oil & Cas Lease No. B 7896	

L'O' Box 1300! Hoopet Live	1.0. Dux 20		1 30-025-31109		
DISTRICT II P.O. Drawer DD, Artesla, NM 88210 Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease STATE X FEE		
DISTRICT III IUXI Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Cas Lease No. B 7896		
	THE PERCENT ON WE	116			
SUNDRY NOTICES	7. Lease Name or Unit Agreement Name				
( DO NOT USE THIS FORM FOR PROPOSE DIFFERENT RESERVOIL	7. Lease White or Oak Agreement				
(FORM C-101)	Lovington Paddock Unit				
1					
1. Type of Well: OR. OAS WELL					
**************************************	OTHER		8. Well No.		
2. Name of Operator	8. Well No. 95				
GREENHILL PETROLEUM CORP	9. Pool name or Wildcat				
3. Address of Operator	Lovington Paddock				
11490 WESTHEIMER, SUITE	200/HOUSTON, TEXAS	77077-0041	Lovington radacak		
A Well Location	•		rate west. Une		
Unit Letter :1585	Feet From The South	Line and432	Feet From The West Line		
<b>5</b> 5	4.5.0	27 F	NMPM Lea County		
Section 31	Township 16 S	Range 37 E	NMPM Lea County		
77777777777777777777777777777777777777					
<i>\////////////////////////////////////</i>	3819'	iK	VIIIIIIIIIIIIII		
Check Apr	propriate Box to Indicate	Nature of Notice, I	Report, or Other Data		
II. Check App	ITION TO:	I SUI	BSEQUENT REPORT OF:		
NOTICE OF INTER	TION TO:				
П	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING L		
PERFORM REMEDIAL WORK	PLUG AND ABANDON C	l i	C ADAMSONATAT		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	IG OPNS. PLUG AND ABANDONMENT L		
		CASING TEST AND	EMENT JOB L		
PULL OR ALTER CASING L_	<del></del>				
OTHER:		OTHER: STIME	ulate and chemical squeezeL		

- 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
  - 7-07-93 Pumped 1000 gallons 15% NEFE HCl acid. Flushed with 50 bbls fresh water.
  - Pumped 20 bbls lease oil with anti-sludge chemicals. Followed with 1000 7-08-93 gallons 15% NEFE HCl acid. Pumped chemical squeeze - 110 gals SCW-0260H in 13 bbls fresh water and flushed with 160 bbls fresh water mixed with 5 gallons DMW-2336D. SI 24 hrs. Returned to production.

I hereby excity that the information above is true and complete to the best of my knowledges	e and beller. THUE Land Manager/Permian Basin	7-14-93 (713) 589-848
TYTEORPRONT NAME Michael J. Newport		тет вы юне но.
(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR		JUL 19 1993
ATROYED BY.	- m.i	_ <del>_</del>