

Submit 3 Copies To Appropriate District  
Office:

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO. 30-025-31226
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: McMillian 34
8. Well No. 1
9. Pool name or Wildcat NE Pollock Wolfcamp
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3760 GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
Hunt Petroleum (AEC), Inc.

3. Address of Operator  
P. O. Box 1350, Houston, TX 77251-1350

4. Well Location  
Unit Letter C : 400 feet from the North line and 1980 feet from the West line  
Section 34 Township 14S Range 38E NMPM County Lea

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU Workover Rig.  
Pulled rods and tubing.  
TIH with packer and bridge plug.  
Located casing leak from 6187' - 6218'.  
RU Schlumberger. Squeezed casing leak with 100 sxs Class H with .2 lb/sk D65 & .2 lb/sk D46.  
WOC.  
POOH with pkr.  
TIH with bit and scraper. Drilled out cement. Tested casing to 1000# for 15 min. Slight leak.  
POOH with bit and scraper.  
TIH and retrieve brige plug (RBP). POOH with RBP.  
RIH with 5-1/2" Lok-set pkr, 2-7/8" SN and 296 jts 2-7/8" 6.5# tbg. Set pkr @ 9290'. Ran rods and hung on.  
Returned well to production 9/6/02.  
NEEA PRESSURE CHART 300# FOR 15 MIN.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Victoria Guidry TITLE Regulatory Coordinator DATE 10/1/02

Type or print name Victoria Guidry Telephone No. (713) 871-3444  
(This space for State use)

APPROVED BY [Signature] TITLE [Signature] DATE OCT 16 2002  
Conditions of approval, if any: [Signature]