

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-31249
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LG-0030 & LG-3974
7. Lease Name or Unit Agreement Name	T.C.H. Ranch '6'
8. Well No.	1
9. Pool name or Wildcat	Kemnitz (Canyon)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Kaiser-Francis Oil Company	
3. Address of Operator P. O. Box 21468, Tulsa, OK 74121-1468	
4. Well Location Unit Letter X : 660 Feet From The South Line and 660 Feet From The East Line Section 6 Township 16S Range 34E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4152' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 11450' w/30' cmt on top. Tagged @ 11410'.
2. Mixed mud and circ'd hole.
3. Spotted 25 sxs cmt @ 9650'-9550'.
4. Spotted 25 sxs cmt @ 6000'-5900'.
5. Cut off 5 1/2" casing @ 5500'. TOOH & LD.
6. Spotted 45 sxs cmt @ 5550'. No tag.
7. Spotted 45 sxs cmt @ 5550'-5450'. Tagged plug @ 5435'.
8. Spotted 60 sxs cmt @ 4550'. Tagged plug @ 4415'.
9. Spotted 60 sxs cmt @ 2570'-2470'.
10. Spotted 45 sxs cmt @ 475'. Tagged plug @ 349'.
11. Spotted 10 sxs cmt @ 30' to surface.
12. Installed dry hole marker.

Plugging operations began 5/24/01 and completed 5/31/01.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Charlotte Van Valkenburg TITLE Technical Coordinator DATE 7/20/01  
TYPE OR PRINT NAME Charlotte Van Valkenburg 918-491-4314 TELEPHONE NO.

(This space for State Use)

COMPLIANCE OFFICER

APPROVED BY Billy E. Prineas TITLE MAF DATE 7/20/01

CONDITIONS OF APPROVAL, IF ANY:

GWW

