

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-32293
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-4119
7. Lease Name or Unit Agreement Name Gecko State -35-
8. Well No. 1
9. Pool name or Wildcat Casey (Strawn) 10310
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3762' DF 3774' KB 3775'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Gecko, Inc.
3. Address of Operator 310 W. Wall, Suite 702-LB106, Midland, TX 79701

4. Well Location Unit Letter <u>B</u> : <u>434</u> Feet From The <u>North</u> Line and <u>1762</u> Feet From The <u>East</u> Line Section <u>35</u> Township <u>16S</u> Range <u>37E</u> NMPM <u>Lea</u> County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3762' DF 3774' KB 3775'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spud (re-entered) well 3/26/94.
2. Drilled surface plug from 0-155'. Drilled out plugs at 4454' and 6386'. Cleaned out hole to 9250'.
3. Spot 240 sxs Class -H- kick-off plug from 9246-8723'.
4. Kick-off hole and started directional drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve L. Thomson TITLE President DATE 4/6/94
TYPE OR PRINT NAME Steve L. Thomson TELEPHONE NO. (915) 686-0121

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Orig. Signed by
Paul Kautz
Geologist

APR 08 1994