

**DISTRICT I**  
P. O. Box 1980, Hobbs, NM 88240

**DISTRICT II**  
P. O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P. O. Box 2088  
Santa Fe, NM 7504-2088

WELL API NO. 30-025-32425
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2148
7. Lease Name or Unit Agreement Name Caprock Maljamar Unit
8. Well No. 165
9. Pool name or Wildcat Maljamar Grayburg San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4205' GR

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> WELL <input type="checkbox"/> OTHER TA	
2. Name of Operator The Wiser Oil Company	
3. Address of Operator P.O. Box 2568 Hobbs, New Mexico (505) 392-9797	
4. Well Location Unit Letter <u>M</u> : <u>66</u> Feet From The <u>South</u> Line and <u>1256</u> Feet From The <u>West</u> Line Section <u>17</u> Township <u>17S</u> Range <u>32E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4205' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
<b>NOTICE OF INTENTION TO</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Temporary Abandon</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/14/00 MIRU Key Well Service. Blew well down to hot oiler. ND WH. POH w/rods and pump. RU BOP. POH w/2-7/8" tbgr. RU Computalog. RIH and set 5-1/2" CIBP @ 4120'. Capped with 10 sks. cement. RD Computalog.

12/15/00 RIH w/2-7/8" tbgr. to 4090'. RU pump truck. Pumped 100 bbls. pkr. fluid down csg and up tbgr. POH. LD 2-7/8" tbgr. NU WH with 2-7/8" x 2' sub and 1 jt. 2-7/8" tbgr. hanging. Topped off csg. w/pkr. fluid. Tested w/chart to 300# for 15 min. Held ok. RDMO. Well is TA'D.

This Approval of Temporary  
Abandonment Expires 11/12/2006

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Production Tech II DATE December 19, 2000  
TYPE OR PRINT NAME Mary Jo Turner TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

