Submit 3 Copies State of New Mexico to Appropriate Energy, Anerals and Natural Resources Department District Office		Form C-103 Revised 1-1-89	
DISTRICT I OIL CONSERVATION DIVISION P. O. Box 1980, Hobbs, NM 88240 2040 South Pacheco WELL API NO.			
Santa Fe, New Mexico 86595		WELL API NO. 30-025-32580	
DISTRICT II		5. Indicate Type of Lease	
P. O. Drawer DD, Artesia, NM 88210		STATE X FEE	
DISTRICT III 1000 Die Prozes D.d. Artes NM 97410		6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd., Aztec, NM 87410		VA-903	
SUNDRY NOTICES AND REPORTS ON WE	LLS		
		Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT		Gecko State "36"	
(FORM C-101) FOR SUCH PROPOSALS)  1. Type of Well:			
Oil Gas			
Well X Well OTHER			
2. Name of Operator	8.	Well No.	
TMBR/Sharp Drilling, Inc.		1	
3. Address of Operator 9. P		Pool name or Wildcat	
P. O. Drawer 10970, Midland, TX 79702		Shipp (Strawn)	
4. Well Location			
Unit Letter E : 2414 Feet From The North	Line and11	09 Feet From The West	
Section 36 Township 16S Range 37E NMPM County Lea			
10. Elevation (Show whether DF, RKB, RT, GR, etc.)			
11.       Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data         NOTICE OF INTENTION TO:       SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON X			
PULL OR ALTER CASING			
OTHER:	OTHER:		
<ul> <li>12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.</li> <li>05/06/99 RIH w/4-1/2" impression block, tagged @ 6765'. POH w/block. Showed 5-1/2" csg to be parted.</li> </ul>			
05/11/99 GIH w/5-1/2" cement retainer and set at 6396'. Sting out and circulate hole. Sting into retainer, cement with 300 sx Cl "H", squeeze to 2800 psi. Sting out and spot 120 sx Cl "H" cement on top of retainer. POH w/tbg.			
05/12/99 GIH w/tbg to 4530. Spot 25 sx cement plug. POH w/tbg. ND wellhead. PU on 5-1/12" csg. Cut 5-1/2" csg at 2950'.			
(continued on separ	ate page)		
I hereby certify that the information above is true and complete to the Bost of my knowledge and i	elief.		
SIGNATURE	Production Manager	date 01/31/02	
TYPE OR PRINT NAME LONNIE Arnold		TELEPHONE NO. (915) 699-5050	
(This space for State Use) APPROVED BY Bully & Muthac TITLE	COMPLIANCE OFFICE		
CONDITIONS OF APPROVAL, IF ANY:			
CONDITIONS OF AFFROVAL, IF ANY:			

**د** د ر TMBR/SHARP DRILLING, INC. <u>Gecko State 36 No. 1</u> 2414' FNL & 1109' FWL Sec. 36, T-16S, R-37E Lea County, NM

## 13. Describe Proposed or Completed Operations (Clearly state all previous details, and give pertinent dates, including date of starting any proposed work) SEE RULE 1103

(Continued)

- 05/13/99 Pull and lay down 5½" csg. NU wellhead. GIH w/tbg to 3000'. Spot 50 sx Cl "C" cement plug. POH w/tbg.
- 05/14/99 GIH w/tbg. Tagged cement plug at 2800'. Circulate hole w/9# mud. Pull tbg to 2125'. Spot 40 sx Cl "C" cement plug. POH w/tbg to 500'. Spot 40 sx Cl "C" cement plug. POH w/tbg to 30'. Circ 10 sx cement plug to surface. Well P&A'd.