

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

LM 30-025-32875

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

MARY 33

8. Well No.

1

9. Pool name or Wildcat

WEST KNOWLES DEVONIAN

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

ANSON GAS CORPORATION

3. Address of Operator

P O BOX 24060 OKLAHOMA CITY, OK 73124

4. Well Location

SHL Unit Letter E : 2040 Feet From The NORTH Line and 2310 Feet From The WEST Line
BHL C 1294 NORTH 2537 WEST
Section 33 Township 16S Range 38E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3710' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/8/97 MIRU Sierra Well Service. Rev circ jet pump out of hole. ND tree, NU BOP's. Rel pkr, Circ hole full of 9.2 ppg plug mud, TOH w/2 7/8" tbg. TIH & set CIBP @13000'. RIH w/40 jts 2 7/8" tbg. 5/9/97 ND BOP, spacer spools & tbg head. Weld 5 1/2" pull sub. Pull stretch - shows free fr 5500-5800'. NU BOP's. TIH w/206 jts 2 7/8" tbg. Spot 25 sx cmt plug fr 6500-6247'. POH, LD 20 jts. 5/12/97 ND BOP's. Run stretch on csg & cut csg @ 5772'. POH & LD 5 1/2" csg (7440' 5 1/2" 17# N-80 left in hole) . NU tbg head, spacer spools & BOP. TIH w/185 jts 2 7/8" tbg. Spot 60 sx cmt plug @ 5838'. POH w/30 jts. 5/13/97 TIH & tag cmt @ 5773'. Spot cmt plug fr 5773-5659' (40 sx). Total plug fr 5838-5659'. LD 39 jts tbg. Spot 60 sx cmt plug fr 4545-4300'. Pull end of tbg to 2146'. Spot 30 sx cmt plug fr 2146-2036'. Pull end of tbg to 505'. Spot 30 sx cmt plug fr 505-395'. TOH w/tbg. ND BOP, spacer spool & tbg head. Spot 10 sx cmt fr 35-3'. Cut off & weld on ID marker. Sold oil inventory & cleaned tanks.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

DANIEL W. FISCHER

TITLE

OPERATIONS MANAGER

DATE

6/2/97

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY

Jack Griffin

TITLE

OIL & GAS INSPECTOR

DATE

CONDITIONS OF APPROVAL, IF ANY: