Form 3160-5 (November 1983) (Formerly 9-331)

## UNITL. STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATES

(Other Instructions on reverse side )

BOX 1980

W MEXICO 88240 Budget Bureau No. 1004-0135 Expires August 31, 1985

BUREAU OF LAND MANAGEMENT			5. LEASE DESIGNATION AND SERIAL NO. LC-064150		
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT - " for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
OIL X GAS OTHER WELL WELL			7. UNIT AGREEMENT NAME  Maljamar Grayburg Unit		
2. NAME OF OPERATOR  The Wiser Oil Company			8. FARM OR LEASE NAME		
3. ADDRESS OF OPERATOR 8115 Preston Road, Suite 400, Dallas, TX 75225			9. WELL NO. 106		
<ol> <li>LOCATION OF WELL (Report location clearly and in accordance with any State requirements.</li> <li>See also space 17 below.)</li> <li>At surface</li> </ol>			10. FIELD AND POOL, OR WILDCAT  Maljamar Grayburg San Andres  11. SEC., T., R., M., OR BLK. AND		
1534' FNL & 1372' FWL, Unit F			SURVEY OR AREA 10, T17S-R32E, NMPM		
14. PERMIT NO. API # 30-025-33039	ELEVATIONS (Show whether DF, R 4148' GR	T, GR, etc.)	12. COUNTY OR PARISH Lea	13. STATE NM	
	ropriate Box to indicate Nature	e of Notice, Report, or Othe	<del></del>	1 11/12	
NOTICE OF INTENTION TO:			BSEQUENT REPORT OF:		
FRACTURE TREAT SHOOT OR ACIDIZE  REPAIR WELL  CH	ULTIPLE COMPLETE  BANDON*  HANGE PLANS		f multiple completion on Well	G CASING X	
(Other)  17. DESCRIBE PROPOSED OR COMPLETED Coproposed work. If well is directionally drilled.	d, give subsurface locations and measur	nent details, and give pertinent dates red and true vertical depths for all n	narkers and zones pertinent to	tarting any this work.)	
1/20/96 Perforate 4261, 67, 76, 77, 81, 4301, 02, 03, 06, 09, 20, 29, 31 & 36 (15 holes). Acidize perfs 4261'-4336' w/3000 gals 15% NEFE acid.					
1/22/96 Perforate 4139, 57	', 66, 67, 70, 74, 78 & 79 (8	3 holes). Acidize perfs 413	39'-4179' w/3000 gal	15% NEFE acid.	
1/24/96 Perforate 3881, 82, 83, 89, 90, 93, 3912, 15, 18, 20, 22, 23, 34, 44, 48, 60, 4014, 18, 37, 40 & 41 (22 holes). Acidize perfs 3881'-4041' w/3000 gals 15% NEFE acid.					
1/26/96 Frac perfs 3881'-4	041' w/55,000 gals 25# Bor	ragel w/50,000# 20/40 sa	nd & 30,000# 16/30	sand.	
18. I hereby certify that the foregoing is true and co SIGNED Michael R. Burch. CPL		The Wiser Oil Company	date <b>4-24-</b> 96		
(This space for Federal or State office use)			D. ATTT	_	
APPROVED BY	TITLE	······································	_ DATE	ms	

\*See Instruction On Reverse Side

