OCD-HOBBS

Form 3160-5 (November 1983) (Formerly 9-331)

UNITE TATES DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICA...*
(Other Instructions on reverse side)

Budget Bureau No. 1004-0135 Expires August 31, 1985

BUREAU OF LAND MANAGEMENT			5. LEASE DESIGNATION AND SERIAL, NO. NM-09015						
(Do not use this for	NOTICES AND REPORTS On for proposals to drill or to deepen or plug back to "APPLICATION FOR PERMIT - " for such proposals to the proposals to drill or to deepen or plug back to "APPLICATION FOR PERMIT - " for such proposals to the proposals to	a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME						
1. OIL GAS WELL OTHER 2. NAME OF OPERATOR The Wiser Oil Company 3. ADDRESS OF OPERATOR P.O. Box 2568 Hobbs, New Mexico 88241			7. UNIT AGREEMENT NAME Maljamar Grayburg Unit 8. WELL NAME AND NO. 89 9. API WELL NO. 30-025-33048						
					 LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 			10. FIELD AND POOL, OR WILDCAT Maljamar Grayburg San Andres 11. SEC., T., R., M., OR BLK. AND	
					1275' FSL & 2525' FEL Unit O			SURVEY OR AREA Sec. 4-T17S-R32E	
					14. PERMIT NO	15. ELEVATIONS (Show whether DF, 4078' GR	RT, GR, etc.)	12. COUNTY OR PARISH Lea County	13. STATE NM
16. (Check Appropriate Box to indicate Natu	re of Notice, Report, or Othe	r Data						
NOTICE OF INTENTION TO:			SSEQUENT REPORT OF:						
TEST WATER SHUT OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL						
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING	3					
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT *						
REPAIR WELL CHANGE PLANS (Other)(Note: Report			f multiple completion on Well						
(Other) Temporary Abandon			ompletion or Recompletion Report and	Log form.)					
	OMPLETED OPERATIONS: (Clearly state all pert tionally drilled, give subsurface locations and meas								
Wiser requests approval to Temp	orarily Abandon the well by the procedure listed be	low.							
Perforations: 3858'-4027' Gray	burg 4051'-4105' Vacuum 4286'-4318' Sa	n Andres Three Fingers							
1. MIRU. 2. TIH w/CIBP.			3	.					
3. Set CIBP @ 3800'. 4. Circulate packer fluid.			5 000 AM 5	,)					
5. Pressure test plug and casing to 500# with chart. (30 min.) 6. POH and lay down tbg.			3	2					
Well is TA.	W			:					
Note: Contact Q&D before beginn	ning work.		3						
18. I hereby certify that the foregoing	is true and correct.								
SIGNED X/, M.	TITLE Superintendent	t .	DATE <u>October 17, 2001</u>						
(This space for Federal or State offi									
APPROVED BY (ORIG. SC CONDITIONS OF APPROVAL, I	TOOL DOWN ON AN AND STANFE	troleum Engineer	DATE ///30/2001						

*See Instruction On Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



TMUSH FOR THE CHARLES

2001 001 1 9 VII 10: 32

BECEIVED