

DISTRICT I  
1625 French Drive Hobbs, NM 88240

DISTRICT II  
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P. O. Box 2088  
Santa Fe, NM 7504-2088

WELL API NO.	30-025-33083
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-2148

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name  
Caprock Maljamar Unit

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
The Wiser Oil Company

8. Well No.  
175

3. Address of Operator  
P.O. Box 2568 Hobbs, New Mexico (505) 392-9797

9. Pool name or Wildcat  
Maljamar Grayburg San Andres

4. Well Location  
Unit Letter D : 1302 Feet From The North Line and 1367 Feet From The West Line  
Section 19 Township 17S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
4105' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐


12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Wiser requests approval to Temporarily Abandon the well by the procedure listed below.

Perforations: 4086'-4571'

1. TIH & set CIBP @ 4000'. Dig and line a workover pit prior to rigging up. Hook up vac. truck to csg. while doing job.
2. Pressure test plug and casing to 500#.
3. If holds circulate pkr. fluid.
4. Pressure test casing to 500# with a pressure recorder.
5. Shut well in.

\*Note: Call OCD before beginning work. No equipment in the hole.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Jones by MST TITLE Superintendent DATE August 16, 2002  
TYPE OR PRINT NAME Mike Jones TELEPHONE NO. (505) 392-9797

(This space for State Use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY  
GARY W. WINK TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
OC FIELD REPRESENTATIVE II/STAFF MANAGER

AUG 21 2002