

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
310 Old Santa Fe Trail, Room 206  
Santa Fe, New Mexico 87503

WELL API NO.

30-025-33090

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

T. D. Pope

8. Well No.

33

9. Pool name or Wildcat

Denton (Devonian)

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

Collins & Ware, Inc.

3. Address of Operator

508 W. Wall, Suite 1200, Midland, Texas 79701

4. Well Location

Unit Letter G : 1458 Feet From The North Line and 1347 Feet From The East Line

Section 35 Township 14-S Range 37-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3808' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Production Casing & Start Completion ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran total of 8 DST's

3/2/96 Ran 5 1/2" casing to 13,160'. Cemented w/ DV tool @ 9962', 1st stage 875 sacks of 35/65 H Poz w/ additives, 2nd stage 600 sacks 35/65 H Poz w/ additives. Release rig @ 4:00 AM 3/3/96.

3/12/96 Spot 500 gal 15% NeFe DI HCl @ 12,690'.

3/13/96 Run CBL - TOC @ 6100'. PBTD @ 13,055'.

Perforated from 12,674'-12,678', 10 holes 2 JSPF

3/14/96 Set RBP @ 12,700'. Pull up & spot 500 gal 15% NeFe HCl @ 12,680'. Swabbed.

3/15/96 to 3/17/96 - Swabbing. Shut well in.

3/18/96 Swabbed. Set RBP @ 12,667'. Spot 500 gal 15% NeFe HCl from 12,165'12,665'.

3/19/96 Perforated from 12,656-12,661' and 12,626-31 12', 24 holes 2 JSPF

3/20/96 Set Pkr @ 12,400' & begin swabbing.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Production Clerk

DATE

3/22/96

TYPE OR PRINT NAME

Dianne Sumrall

TELEPHONE NO. (915) 687-3435

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

MAR 26 1996

CONDITIONS OF APPROVAL, IF ANY:

