

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	GEOLOGIC MARKERS	
				NAME	TOP MEAS. DEPTH VERT. DEPTH
	0'		Caliche & Redbed	B. Salt	2130'
	1010'		Anhydrite	T. Yates	2329'
	1160'		Salt	T. Seven Rivers	2600'
	2130'		Dolomite, Sand & Anhydrite	T. Queen	3265'
	4200'			T. Grayburg	3707'
				T. San Andres	3999'

RECEIVED
1976 OCT 22 A 428
ROSEAU LAND MINE
ROSWELL OFFICE