APPROVED BY -

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy Minerals and Natural Resources Department

Form C-101 Revised 1-1-89

DISTRICT I P.O. Rox 1980. Hobbs, NM \$8240

OIL CONSERVATION DIVISION WELL APLNO

		Fe Trail,		
Santa	Fe, No	w Mexic	x 8750	<b>)</b> 3

	310 Old Santa Fe Trail, Room 206			
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	i∞ 87503	30-025-3 <del>3776</del> 3373		
DISTRICT III			5. Indicate Type of Lease STATE	FEE X
1000 Rio Brazos Rd., Azzec, NM 87410			6. State Oil & Gas Lease No.	
	S AND REPORTS ON WE			
_	IR. USE "APPLICATION FOR PE		7. Lease Name or Unit Agreement Name	
(FORM C-101	) FOR SUCH PROPOSALS.)		BUS BARN 4	
OIL X WELL X	OTHER			
2. Name of Operator		·····	8. Well No.	
Chesapeake Operating, 1  Address of Operator	Lnc.		9. Pool same or Wildcat	
P. O. Box 18496, Oklaho	oma City, OK 73154-0	496	West Lovington Strawn	
Unit Letter T : 2190	Feet From The South	Line and 870	840 Feet From The West	Line
,	1/0		T. F. A.	
Section 4	Township 16S R 10. Elevation (Show whether	lange 36E 1 or DF, RKB, RT, GR, etc.)	NIMPM LEA	County
	GR: 3926'		<i>\\\\\\\\\\</i>	
	propriate Box to Indicate	•	_	
NOTICE OF INTENTION TO:			SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	닏
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDOI	NMENT [
PULL OR ALTER CASING	_	CASING TEST AND CE	MENT JOB	_
OTHER:		OTHER: Casing	& Plug	<u></u> <u> </u>
	(Clambs state all aminus desails	and give pertinent dates inch	uding estimated date of starting any proposed	
12. Describe Proposed or Completed Operations	(Citarry state an perioden acians,	and give possible and, see		1
work) SEE RULE 1103. 01-02-97 Run 11 its 48# H	H40 ST&C Csg to 450'	; shoe @ 404'; ce		•
work) SEE RULE 1103. 01-02-97 Run 11 its 48# I =13-3/8" Casing	H40 ST&C Csg to 450' ; WOC: 8 hrs 14	; shoe @ 404'; ce .8 ppg, 1.34 yiel	Ld	
01-02-97 Run 11 its 48# I =13-3/8" Casing 01-07-97 Run 2 jts 8-5/8	H40 ST&C Csg to 450' WOC: 8 hrs 14' 32# J55 ST&C csg;	; shoe @ 404'; co .8 ppg, 1.34 yiel 64 jts 28# J55 S'	Id I&C csg; 33 jts 32# J55	
01-02-97 Run 11 its 48# I =13-3/8" Casing 01-07-97 Run 2 jts 8-5/8	H40 ST&C Csg to 450' WOC: 8 hrs 14' 32# J55 ST&C csg;	; shoe @ 404'; ce .8 ppg, 1.34 yiel 64 jts 28# J55 S' ar @4154' & shoe 7 yield; tal 200	Id I&C csg; 33 jts 32# J55 @ 4198.62' +260 sx Prem, 14.8 ppg & 1.32	
01-02-97 Run 11 its 48# I =13-3/8" Casing 01-07-97 Run 2 jts 8-5/8	H40 ST&C Csg to 450'; WOC: 8 hrs 14' 32# J55 ST&C csg; 1 99 jts; float coll k HCP, 12.7 ppg, 1.9	; shoe @ 404'; ce .8 ppg, 1.34 yiel 64 jts 28# J55 S' ar @4154' & shoe 7 yield; tal 200	Id I&C csg; 33 jts 32# J55 @ 4198.62' +260 sx Prem, 14.8 ppg & 1.32	
work) SEE RULE 1103.  01-02-97 Run 11 its 48# I =13-3/8" Casing  01-07-97 Run 2 jts 8-5/8'  ST&C csg - total cement w/1100 ss WOC: 9-1/2 hrs  Casing collapsed at 4200'	H40 ST&C Csg to 450'; WOC: 8 hrs 14' 32# J55 ST&C csg; 1 99 jts; float coll k HCP, 12.7 ppg, 1.9	; shoe @ 404'; ce .8 ppg, 1.34 yiel 64 jts 28# J55 S' ar @4154' & shoe 7 yield; tal 200	Id I&C csg; 33 jts 32# J55	
### SEE RULE 1103.  01-02-97 Run 11 its 48# I =13-3/8" Casing  01-07-97 Run 2 jts 8-5/8" ST&C csg - total cement w/1100 st WOC: 9-1/2 hrs  Casing collapsed at 4200"  01-11-97 Lead in cement tail in cement w	H40 ST&C Csg to 450'; WOC: 8 hrs 14'; 32# J55 ST&C csg; 1 99 jts; float coll K HCP, 12.7 ppg, 1.9  - rig moved 30' Eas W/30 sx prem. 1050-9 W/30 sx prem neat 4	; shoe @ 404'; ce .8 ppg, 1.34 yiel 64 jts 28# J55 S ar @4154' & shoe 7 yield; tal 200 t	Id I&C csg; 33 jts 32# J55 @ 4198.62' +260 sx Prem, 14.8 ppg & 1.32	
### SEE RULE 1103.  01-02-97 Run 11 its 48# I =13-3/8" Casing  01-07-97 Run 2 jts 8-5/8" ST&C csg - total cement w/1100 st WOC: 9-1/2 hrs  Casing collapsed at 4200"  01-11-97 Lead in cement tail in cement w	H40 ST&C Csg to 450'; WOC: 8 hrs 14' 32# J55 ST&C csg; 1 99 jts; float coll K HCP, 12.7 ppg, 1.9  - rig moved 30' Eas	; shoe @ 404'; ce .8 ppg, 1.34 yiel 64 jts 28# J55 S ar @4154' & shoe 7 yield; tal 200 t	Id I&C csg; 33 jts 32# J55 @ 4198.62' +260 sx Prem, 14.8 ppg & 1.32	
### SEE RULE 1103.  01-02-97 Run 11 its 48# I =13-3/8" Casing  01-07-97 Run 2 jts 8-5/8" ST&C csg - total cement w/1100 st WOC: 9-1/2 hrs  Casing collapsed at 4200"  01-11-97 Lead in cement tail in cement w	H40 ST&C Csg to 450'; WOC: 8 hrs 14'; 32# J55 ST&C csg; 1 99 jts; float coll K HCP, 12.7 ppg, 1.9  - rig moved 30' Eas W/30 sx prem. 1050-9 W/30 sx prem neat 4	; shoe @ 404'; ce .8 ppg, 1.34 yiel 64 jts 28# J55 S ar @4154' & shoe 7 yield; tal 200 t	Id I&C csg; 33 jts 32# J55 @ 4198.62' +260 sx Prem, 14.8 ppg & 1.32	
### SEE RULE 1103.  01-02-97 Run 11 its 48# I =13-3/8" Casing  01-07-97 Run 2 jts 8-5/8" ST&C csg - total cement w/1100 st WOC: 9-1/2 hrs  Casing collapsed at 4200"  01-11-97 Lead in cement tail in cement w	H40 ST&C Csg to 450'; WOC: 8 hrs 14'; 32# J55 ST&C csg; 1 99 jts; float coll K HCP, 12.7 ppg, 1.9  - rig moved 30' Eas W/30 sx prem. 1050-9 W/30 sx prem neat 4	; shoe @ 404'; ce .8 ppg, 1.34 yiel 64 jts 28# J55 S ar @4154' & shoe 7 yield; tal 200 t	Id I&C csg; 33 jts 32# J55 @ 4198.62' +260 sx Prem, 14.8 ppg & 1.32	
### SEE RULE 1103.  01-02-97 Run 11 its 48# I =13-3/8" Casing  01-07-97 Run 2 jts 8-5/8" ST&C csg - total cement w/1100 st WOC: 9-1/2 hrs  Casing collapsed at 4200"  01-11-97 Lead in cement tail in cement w	H40 ST&C Csg to 450'; WOC: 8 hrs 14' 32# J55 ST&C csg; 1 99 jts; float coll k HCP, 12.7 ppg, 1.9 - rig moved 30' Easw/30 sx prem. 1050-9w/30 sx prem neat 4 rem neat 60' to sur	; shoe @ 404'; ce .8 ppg, 1.34 yiel 64 jts 28# J55 S' ar @4154' & shoe 7 yield; tal 200 t	Id I&C csg; 33 jts 32# J55 @ 4198.62' +260 sx Prem, 14.8 ppg & 1.32	
### SEE RULE 1103.  01-02-97 Run 11 its 48# I =13-3/8" Casing  01-07-97 Run 2 jts 8-5/8" ST&C csg - total cement w/1100 st WOC: 9-1/2 hrs  Casing collapsed at 4200"  01-11-97 Lead in cement tail in cement top out 10 sx process.	H40 ST&C Csg to 450' NOC: 8 hrs 14 32# J55 ST&C csg; 1 99 jts; float coll K HCP, 12.7 ppg, 1.9 - rig moved 30' Eas W/30 sx prem. 1050-9 W/30 sx prem neat 4 rem neat 60' to sur	; shoe @ 404'; ce .8 ppg, 1.34 yiel 64 jts 28# J55 S' ar @4154' & shoe 7 yield; tal 200 t	Id  I&C csg; 33 jts 32# J55  @ 4198.62' 4260  sx Prem, 14.8 ppg & 1.32  Poud /-/-97  D 1650	yield
work) SEE RULE 1103.  01-02-97 Run 11 its 48# I =13-3/8" Casing  01-07-97 Run 2 jts 8-5/8' ST&C csg - total cement w/1100 st WOC: 9-1/2 hrs  Casing collapsed at 4200'  01-11-97 Lead in cement total in cement to top out 10 sx processory.	H40 ST&C Csg to 450'; WOC: 8 hrs 14 '32# J55 ST&C csg; 1 99 jts; float coll k HCP, 12.7 ppg, 1.9 - rig moved 30' Eas w/30 sx prem. 1050-9 w/30 sx prem neat 4 rem neat 60' to sur	; shoe @ 404'; ce .8 ppg, 1.34 yiel 64 jts 28# J55 S' ar @4154' & shoe 7 yield; tal 200 t	Id  I&C csg; 33 jts 32# J55  @ 4198.62' 4260  sx Prem, 14.8 ppg & 1.32  Poud /-/-97  D 1650	yield
Ol-02-97 Run 11 its 48# I =13-3/8" Casing Ol-07-97 Run 2 jts 8-5/8' ST&C csg - total cement w/1100 st WOC: 9-1/2 hrs  Casing collapsed at 4200'  Ol-11-97 Lead in cement tail in cement to tail in cement to top out 10 sx pt	H40 ST&C Csg to 450' NOC: 8 hrs 14 32# J55 ST&C csg; 1 99 jts; float coll K HCP, 12.7 ppg, 1.9 - rig moved 30' Eas W/30 sx prem. 1050-9 W/30 sx prem neat 4 rem neat 60' to sur	; shoe @ 404'; ce .8 ppg, 1.34 yiel 64 jts 28# J55 S' ar @4154' & shoe 7 yield; tal 200 t	Id  I&C csg; 33 jts 32# J55  @ 4198.62' +260  sx Prem, 14.8 ppg & 1.32  Put /-/-97  D 1650  malyst DATE 04-22-97	yield
Ol-02-97 Run 11 its 48# I =13-3/8" Casing Ol-07-97 Run 2 jts 8-5/8' ST&C csg - total cement w/1100 st WOC: 9-1/2 hrs  Casing collapsed at 4200'  Ol-11-97 Lead in cement tail in cement to tail in cement to top out 10 sx pt	H40 ST&C Csg to 450' NOC: 8 hrs 14 32# J55 ST&C csg; 1 99 jts; float coll K HCP, 12.7 ppg, 1.9 - rig moved 30' Eas W/30 sx prem. 1050-9 W/30 sx prem neat 4 rem neat 60' to sur	; shoe @ 404'; ce .8 ppg, 1.34 yiel 64 jts 28# J55 S' ar @4154' & shoe 7 yield; tal 200 t	Id  I&C csg; 33 jts 32# J55  @ 4198.62' +260  sx Prem, 14.8 ppg & 1.32  Put /-/-97  D 1650  malyst DATE 04-22-97	yield

- TITLE -