State of New Mexico Ene ___, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II	2040 Pach Santa Fe,		505		30-025-33733		
P.O. Drawer DD, Artesia, NM 88210					sIndicate Type of Leas	е	
DISTRICT III						STATE	FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410					6State Oil & Gas Lease	e No.	
SUNDRY NOT	ICES AND REPORTS C	N WELL	S				
(DO NOT USE THIS FORM FOR PRO	OPOSALS TO DRILL OR TO D	DEEPEN C	OR PLUG BAC	ктоа	al case Name es Unit		
DIFFERENT RESER	RVOIR. USE "APPLICATION!	FOR PERM	MIT"		7Lease Name or Unit /	agreement name	
	-101) FOR SUCH PROPOSAI	LS.)					
₁Type of Well: OIL ☐ GAS —							
WELL WELL	OTHER				Grasslands "27"		
₂Name of Operator					₀Well No.		* -
Nearburg Producing Company				_	1		
sAddress of Operator					Pool name or Wildcat		
3300 North A Street, Building 2, Su	ite 120, Midland, Texas 79	705			Wildcat-Devonia	n	
4Well Location							
Unit Letter P : 1243	Feet From TheSou	th	_ Line and	353	Feet From The _	East	Line
Section 27			ange	34E	NMPM	Lea	County
	eElevation (Show what 4,071' GR	ether DF, R	RKB, RT, GR, etc.	.)		Trans.	
11 Check A _I	opropriate Box to India	ate Nat	ture of Noti	ice, Rep	ort, or Other D	ata	
NOTICE OF IN	TENTION TO:			SUBS	EQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WO	RK		ALTERING CAS	SING

TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ANBANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB OTHER:

12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set 225' cement plug from 14,427'-14,652'.
- 2) Set 90' cement plug from 12,610'-12,700'.
- 3) Set 106' cement plug from 11,394'-11,500'.
- 4) Set 147' cement plug from 9,353'-9,500'.
- 5) Set 147' cement plug from 7,353'-7,500'.
- 6) Set 163' cement plug from 5,337'-5,500'.
- 7)
- Set 320' cement plug from 2,998'-3,318'. PUH & WOC. TIH & tag cmt @ 3,210'.
- 8) Set 105' cement plug from 1,695'-1,800'.
- 9) Set 39 ' cement plug from surface to 39'. ND BOPE. Cut off csg & cap well.
- RDMO drilling rig. 10)
- P&A'd well. Final report.

I hereby certify that the information of the support of the suppor	ation above is true and complete to the best of my ki	nowledge and belief. тітце Manager of Drilling and Production	DATE 09-25-97
	At Nimbrough		TELEPHONE NO. (915) 686-8235
(This space for State Use) APPROVED BY	Billey E. Frehen	COMPLIANCE OFFICER	DATE SAN 28 7007

CONDITIONS OF APPROVAL, IF ANY: