ubmit 3 Copies To Appropriate District Office State of New Mexico Energy, Minerals and Natural Resources		Form C-103 Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 87240		WELL API NO.	
District II 811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION		DIVISION	30-025-33908
District III 2040 South Pacheco		heco	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
2040 South Pacheco, Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name:
1. Type of Well: Oil Well Gas Well Other			Field
2. Name of Operator Amerind Oil Company Limited Partnership			8. Well No. 1-Y
3. Address of Operator		9. Pool name or Wildcat	
415 West Wall, Suite 500, Midland tX 79701-4467 4. Well Location			South Big Dog Strawn
4. Well Education			
Unit Letter Q: 625 feet from the East line and 1650 feet from the South line			
Section 3	Township 16S Ra	inge 35E	NMPM Lea County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3995 GL, 4013 KB 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			
TEMPORARILY ABANDON 🔲 0	CHANGE PLANS	COMMENCE DRIL	
	MULTIPLE COMPLETION	CASING TEST AN	ABANDONMENT D
OTHER:	CONFERMION	OTHER:	П
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompilation. (Anticipated plugging dated ASAP)			
1. Set CIBP @ 10,250' w/35' cement cap. 2. Displace with 10 lb/gal brine water & 25 lb gel/bbl 3. Plug No. 2 30 sx @ 9950' Plug No. 3 30 sx @ 6535' Plug No. 4 30 sx @ 4797' 4. Cut 5-1/2" casing @ 2400' and recover.			
Plug No. 4 30 sx @ 4797'			
it out to 1/2 subtring a 2100 with recover 1/4/2			
5. Plug No. 5 60 sx Plug No. 6 60 sx @		140	
Plug No. 7 50 sx @ 463'			
Plug No. 8 10 sx @ surface			
 Weld on dry hole marker. Salvage equipment. Clean and level location. Report. 			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE JAMES A CLUSCO TITLE Agent DATE 08/09/2000			
,	<i>'</i>		
Type or print name James E. Yeley / Telephone No. 915/682-8217 (This space for State use)			
APPPROVED BY	TITLE		DATE:
Conditions of approval, if any:	IIILE_	<u> </u>	DATE
THE COMMISSION MUST BE NOTIFIED 28			
PIOURS PRIOR TO THE BITINENING OF			
PLUGGING OPERATIONS FOR THE C403 To be approved.			

S (



\(\sigma_{\sigma}\)