

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-33931
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VA-605
7. Lease Name or Unit Agreement Name Brunson AQK State Com
8. Well No. 1
9. Pool name or Wildcat Wildcat Mississippian

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter <u>G</u> : <u>2260</u> Feet From The <u>North</u> Line and <u>1795</u> Feet From The <u>East</u> Line Section <u>10</u> Township <u>16S</u> Range <u>35E</u> NMPM Lea County	
10. Elevation (Show whether DP, RKB, RT, GR, etc.) 4003' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Perforate & acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-19-97 - Cleaned location and set anchors. Moved in and rigged up pulling unit. Shut down for night.  
9-20-97 - Hooked up accumulator and lines for hydraulic BOP. TIH with bit, scraper and 2-7/8" tubing. Tagged PBTD at 12542'. Laid down 1 joint. Nippled up BOP. Shut in.  
9-21-22-97 - Pickled tubing with 500 gallons 15% HCL acid at 12515'. Reversed acid out. TOOH with bit and scraper. Rigged up wireline. TIH with logging tools and ran CBL/GR log. TOOH with logging tools and rigged down wireline. Shut well in.  
9-23-97 - Rigged up wireline. TIH with 4" casing guns and perforated 12480-12486' w/28 .42" holes (4 SPF - Mississippian). TOOH with casing guns and rigged down wireline. TIH with packer w/1.875" XL on/off tool and tubing. Nippled down BOP and nippled up tree. Set packer at 12421'. Swabbed tubing down.  
9-24-97 - Rigged up treesaver. Acidized perforations 12480-12486' with 1500 gallons 15% iron control HCL acid and ball sealers. Bled well down. Nippled down treesaver. Swabbed. Shut well in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE Sept. 29, 1997  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL FILED IN THIS WILL AMS  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

OCT 17 1997