

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
310 Old Santa Fe Trail, Room 206  
Santa Fe, New Mexico 87503

WELL API NO.

30-025-34106

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

BLACKMON "21"

8. Well No.

1

9. Pool name or Wildcat

West Lovington-Penn

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL

☒

GAS  
WELL

☐

OTHER

2. Name of Operator

Chesapeake Operating, Inc.

3. Address of Operator

P. O. Box 18496, Oklahoma City, OK 73154-0496

4. Well Location

Unit Letter C : 330 Feet From The North Line and 2146 Feet From The West Line

Section

21

Township

16S

Range

36E

NMPM

LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

GR: 3906'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

08/13/99 TOOH w/373 jts 2-7/8" tbg, TIH, set 5-1/2" CIBP @11,700', TIH w/tbg, spot 30 sx cmt on top of plug, circ hole w/mud, TOOH 8675-8575', spot 25 sx cmt, TOOH 6417-6317'

08/14/99 Spot 25 sx @6417'-6317', TOOH to 4275-4175', spot 25 sx cmt, TOOH to 2000'-1900', spot 25 sx cmt, TOOH to 535'-435', spot 35 sx cmt to surface, dig out around wellhead, cut off below surface, weld on cap, dig out anchors, cut off, RDMO rig, cover up hole at well, clean up location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Barbara J. Bale

TITLE

Regulatory Analyst

DATE 08/18/99

TYPE OR PRINT NAME

Barbara J. Bale

TELEPHONE NO. (405) 848-8000

(This space for State Use)

APPROVED BY

Johnny Robinson

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

CWW