

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-34631
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Shell Lusk ANB
8. Well No.	2
9. Pool name or Wildcat	Big Dog Strawn, South
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3990' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: OR WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210	4. Well Location Unit Letter <u>E</u> : <u>1950</u> Feet From The <u>North</u> Line and <u>350</u> Feet From The <u>West</u> Line

Section <u>11</u>	Township <u>16S</u>	Range <u>35E</u>	NMPM	Lea	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3990' GR					

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <u>Perforate & acidize</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-20-99 - Cleaned location. Cut off 7" casing. Installed tubing head. Set anchors. Moved in and rigged up pulling unit.
7-21-99 - TIH with bit, drill collars and 2-7/8" tubing. Tagged DV tool at 8042'. Drilled out DV tool. Tested casing to 1500 psi. TIH and tagged PBTD at 11604'. Pickled tubing with 500 gallons 15% double inhibited HCL acid. Displaced hole with 2% KCL. TOOH. Shut well in.
7-22-99 - Rigged up wireline. TIH with logging tools and ran GR/CBL log. TOOH with logging tools. TIH with 4" casing guns and perforated 11374-11445' w/34 .42" holes as follows: 11374-11375', 11380-11384', 11390-11396', 11410-11414', 11428-11432' and 11436-11445' (1 SPF - Strawn). TOOH with casing guns and rigged down wireline. TIH with 1.81" F nipple, sub, packer with 1.81" XL on/off tool and 2-7/8" tubing. Set bottom of packer at 11313'. Tested annulus to 1500#. Swab & flow testing.
7-23-99 - Flow tested. Acidized perforations 11374-11445' with 4000 gallons 15% iron control HCL acid. Loaded tubing with 38 bbls. Swabbed. Shut down for rig repair (engine).

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE July 26, 1999

TYPE OR PRINT NAME Rusty Klein

TELEPHONE NO. 505/748-1471

(This space for State Use) ORIGINAL SIGNED BY
GARY WINK

APPROVED BY FIELD OFFICIAL TITLE FIELD OFFICIAL DATE NOV 30 1999

CONDITIONS OF APPROVAL, IF ANY: