

Submit 3 Copies To Appropriate  
District Office  
**DISTRICT I**  
1625 N. French Dr., Hobbs, NM 88240  
**DISTRICT II**  
811 South First, Artesia NM 88210  
**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
**District IV**  
2040 S. Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources  
**OIL CONSERVATION DIVISION**  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. 30-025-34718
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator David H. Arrington Oil & Gas, Inc.		6. State Oil & Gas Lease No. 24907
3. Address of Operator P.O. Box 2071 Midland, Texas 79702		7. Lease Name or Unit Agreement Name:  Orange Humpy
4. Well Location Unit letter <u>A</u> : <u>330</u> feet from the <u>North</u> line and <u>990</u> feet from the <u>East</u> line  Section 21 Township 16S Range 36E NMPM County Lea		8. Well No. 1
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR - 3978' KB - 3994'		9. Pool name or Wildcat Diamond Strawn

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  
1/6/00 Contact Gary Wink, OCD, Hobbs, New Mexico, 11:00 am.

Plug and abandon well: Spotted cement plugs. BJ Services, Hobbs

Plug No. 1. 11,685-11,585 40 sx	5. 4,997-4,790 60 sx tagged
2. 9,652-9,552 40 sx	6. 2,187-2,087 35 sx
3. 7,621-7,521 40 sx	7. 500-400 35 sx
4. 6,403-6,303 40 sx	8. Surface 10 sx

1/7/00 Released drilling rig. Well P & A. All cement class H (15.6#/gal)

2/2/00 Cut off casing 3' below ground level. Welded on steel plat with dryhole maker data. Well P & A'd.

Dry hole marker below ground level approved by Gary Wink, OCD, Hobbs, New Mexico

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve Scott TITLE Engineer DATE 2/08/00

Type or print name Steve Scott

Telephone No. 915/682-6685

(This space for State use)

APPROVED BY [Signature] TITLE Asst Rep DATE 1-22-00

Conditions of approval, if any:

GW

8

