Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103
District	Energy, Minerals and Natural Resources		Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240 District II			PI NO. 5030
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		te Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		TATE FEE
District IV	Santa Fe, NM 87505		Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	anta re, NM		
SUNDRY NOTICES AND REPORTS ON WELLS			Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			14" State
PROPOSALS.)			4 State
1. Type of Well: Oil Well Gas Well Other Other Ory Hole			
2. Name of Operator		7. Well	No
David H. Arrington Oil & Gas, Inc		11	1.0.
3. Address of Operator			name or Wildcat
P.O. Box 2071, Midland, Texas 79702		Wildcat; S	Seven Rivers
4. Well Location			
Unit LetterD_:990'	feet from theNorth lin	e and850'feet from	n theWestline
Section 14	Township 16S Rar	ge 35E NMF	PM County Lea
	Elevation (Show whether DR, RA		
3984' GL			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
NOTICE OF INTENTION TO: SUBS			ALTERING CASING
PERFORM REMEDIAL WORK FEOG AND ABANDON			
TEMPORARILY ABANDON CHAI	NGE PLANS 🗆 CO	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND	
СОМ	PLETION CE	MENT JOB	
OTHER:	□ от	HER:	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompilation.			
5/21/00- MIRU, spudded 5/21/00 @ 2:30 p.m.			
5/22/00- Drld 12 1/4" hole to 1930'. Ran 8 5/8" casing 24# at 1930' and cement with 700 sxs Lite + 200 sxs "C". Circ 100 sxs to			
surface. Weld on head & test.			
5/23/00- NU BOP and test. Drill 7 7/8" hole. Drill & survey.			
5/24/00- Drlg, circ, log & DST. 5/25-26/00- DST, drlg, circ, survey & log. Reached TD at 3500'.			
5/27/00- Ream and wash to bottom 180', circ and condition mud & TOH for logs.			
5/28/00- TOH, log & wait on orders.			
5/29/00- P&A well. Released rig @ 2:30 a.m., 5/29/00.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
	TITLE F	ngineer	DATE 7/12/01
SIGNATURE V	IIILEF	igineer	DATE// J @/01
Type or print name Chuck Sledge /	<u></u>	Te	elephone No. (915) 682-6685
(This space for State use)			*.
` .	mini n	Orig. Rigmod v	nate
APPPROVED BY	TITLE	म् स्टब्स	DATE
Conditions of approval, if any:		X. 15	