Submit 3 Copies To Appropriate District Office	State of	State of New Mexico			Form	C-103	
District I	Energy, Minerals and Natural Resources				Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO.			
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION				30-025-35099 5. Indicate Type of Lease			
District III 1220 South St. Francis Dr. 1200 Rio Brazos Rd., Aztec, NM 87410				STATE X FEE			
District IV Santa Fe, NM 87505				6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505							
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name:			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Green Star 14 State			
PROPOSALS.)							
1. Type of Well: Oil Well XX Gas Well C	Other						
2. Name of Operator				8. Well No.			
Texaco Exploration & Production, Inc.				2			
3. Address of Operator				9. Pool name or Wildcat			
P.O. Box 3109 Midland, Texas 79702 4. Well Location				Anderson Ranch	ı Queen		
Unit LetterK	:2308feet from the	South	line and 19	980feet from	n theWe <u>st</u>	line	
Section 14	Township	160	Damos 22E	ND (D) (, G		
Section 14	10. Elevation (Show		Range 32E	NMPM	Lea County		
11. Check	Appropriate Box to I	ndicate N					
NOTICE OF INTENTION TO: SUB				SEQUENT RE			
PERFORM REMEDIAL WORK	PLUG AND ABANDOI	N 🗆	REMEDIAL WOR	к <u>П</u>	ALTERING CASI	NG 🗌	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND	X	
PULL OR ALTER CASING	MULTIPLE		CASING TEST AN	ID 🗇	ABANDONMENT		
	COMPLETION		CEMENT JOB				
OTHER:			OTHER:			П	
12. Describe proposed or complete	d operations. (Clearly st	ate all pert	inent details, and give	ve pertinent dates,	including estimated	date of	
starting any proposed work). Si	EE RULE 1103. For Mu	ıltiple Com	pletions: Attach we	llbore diagram of	proposed completic	n or	
recompilation.							
1. Set 5 ½ CIBP @ 3625 (Que	een) Spot 25 sxs. plug 36	525 to 3425	Tag @ 3328				
2. Displace hole w/MLF, 9.5#	Brine w.25# gel P/BBL			/2	2324252622		
3. Spot 25 sxs. plug 2800 to 2600 (Yates, B-Salt)							
4. Spot 25 sxs. plug 1400 to 1	200 (T-Salt)			1819	Kith to) अ	
 Set 5 ½ CIBP @ 3625 (Queen) Spot 25 sxs. plug 3625 to 3425 Tag @ 3328 Displace hole w/MLF, 9.5# Brine w.25# gel P/BBL Spot 25 sxs. plug 2800 to 2600 (Yates, B-Salt) Spot 25 sxs. plug 1400 to 1200 (T-Salt) Spot 25 sxs. plug 600 to 400 (8 5/8 shoe) Tag @ 331 CIRC cmt. 30 to surf. w/15 sxs., install dry hole marker 2/19/02 							
6. CIRC cmt. 30 to surf. w/15 sxs., install dry hole marker 2/19/02							
				\	STHOIGST.		
I hereby certify that the information	above is true and comple	ata to the h	est of my knowledge	and baliaf			
	•		•	and benen.			
SIGNATURE/	}	_TITLE/	MANAGER		DATE <u>2/19/02</u>	_	
Type or print name /m my	BAGLEY			Telep	hone No. 915683	14996	
(This space for State use)	3//				w	,	
APPPROVED BY Selly &	trulice	TITLE	COMPLIANCE OF	FFICER	DATE	L	
Conditions of approval, if any:							
GWW						691	
S M M						M	

<u>آ</u> د ک

The second second