Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources District I Revised March 25, 1999 1625 N. French Dr., Hobbs, NM 88240 WELL API NO. District II 30-025-35099 OIL CONSERVATION DIVISION 811 South First, Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 STATE 🔼 FEE Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) Green Star 14 State 1. Type of Well: Oil Well Gas Well Other Name of Operator 8. Well No. Texaco Exploration & Production, Inc. 2 Address of Operator 9. Pool name or Wildcat P. O. Box 3109, Midland, TX Anderson Ranch Queen Well Location Unit Letter K : 2308 feet from the South line and 1980 feet from the West Section 14 NMPM Lea Township 16S Range 32E County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK **ALTERING CASING** TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **PULL OR ALTER CASING** MULTIPLE **CASING TEST AND** COMPLETION **CEMENT JOB** OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Set 5 1/2" CIBP @ 3625' (Queen). Spot 25 Sx plug 3625'-3425 WOC Tag 1. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL 2. Spot 25 Sx plug 2800'-2600' (Yates, B-Salt) Spot 25 Sx plug 1400'-1200' (T-Salt) 3. 4. Spot 25 Sx plug 600'-400' (8 5/8" shoe) WOC Tag 5. 6. 10 Sx Surf, Install dry hole marker. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE \_ TITLE FACILITY FNGINGER Type or print name AMES ORBITT Telephone No. (This space for State use) APPPROVED BY TITLE Conditions of approval, if any:

Em P



PLUGGING & ABANDONMENT WORKSHEET (3 STRING CSNG) OPERATOR TEVACO EXPLORATION & PRODUCTION LEASENAME GREEN STAC 14 STATE WELL # Shirt S 16-5 RNG 32-E TWN SECT 2308 N(S)L FROM FORMATION @ TD QUEEN TD: 3907 FORMATION @ PBTD PBTD: MLF TOC SIZE SET @ TOC DETERMINED BY 25/8 **8518** SURFACE 535 ciec SUEF INTMED 1 INTMED 2 TOCSULF 51/2 3907 ciec PROD SUEF TOP SIZE BOT TOC DETERMINED BY LINER 1 MLF LINER 2 CUT & PULL @ TOP - BOTTOM 3685 - 3712 INTMED 1 PERFS INTMED 2 OPENHOLE PROD • REQUIRED PLUGS DISTRICT I PLUG TYPE SACKS DEPTH RUSTLER (ANHYD) PLUG **CMNT** YATES EXAMPLES OUEEN MLF 25 SXS 9850 OН PLUG#1 **GRAYBURG** 50 SXS 8700'-8800' SHOE PLUG#2 SAN ANDRES CIBP/35' 5300° PLUG #3 5300 25 SXS PLUG#3 **CIBP** CAPITAN REEF 50 SXS 4600'-4700' STUB PLUG#4 200 SXS 400 RETNR SQZ DELAWARE MLF PLUG#7 SURF 10 SXS 0-10' BELL CANYON 3625' CIBP PLUG#I CHERRY CANYON QUEEN 255X 3625-34X BRUSHY CANYON PLUG#2 YATE 255x 2800-2600 BONE SPRING PLUG#4 T-SALT 255x 1400-1200 85/83 25 Sx 600-400 PLUG#5 **GLORIETA** SURF 10 SX 10-SURF PLUG#6 TOC RIJNERRY PLUG#7 PLUG#E DRINKARD PLUG#9 ABO PLUG# 10 PLIK)# WC PENN PLUO # STRAWN TD 3907 DEVONIAN

\* \* \*

AUG 200 6 AUG 20

, **5** 5