

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-35109
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.		7. Lease Name or Unit Agreement Name GREEN STAR "22" STATE
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐ NEW WELL ☐	8. Well No. 1	
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.	9. Pool Name or Wildcat ANDERSON RANCH WOLFCAMP	
3. Address of Operator 205 E. Bender, HOBBS, NM 88240		
4. Well Location Unit Letter G : 1980 Feet From The NORTH Line and 2310 Feet From The EAST Line Section 22 Township 16-S Range 32-E NMPM LEA COUNTY		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4312'		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	INTERMEDIATE CASING ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-25-00/10-15-00: RAN 8.875" CSG, 8 JTS 32# NS80 LT&C (345.88') & 90 JTS 32# K-55 LT&C 3640.00'. SET @ 3950'. CENTRALIZERS ON FIRST JT & EVERY 3 JTS- TOTAL OF 10 CENTRALIZERS. CMT W/1180 SX LEAD & 290 SX TAIL. BUMP PLUG @ 1800 W/1700 PSI. CIRC 157 SX. ND. SET SLIPS & CUT OFF 8.625" CSG. TEST BOP. DRILL CMT 3905-3950.4112,4375,4650,4847,5319,5380,5791,5916,6285,6375,6785,6810,6923,7105,7414,7573,7883,8091,8355,8545,8849,9312,9349,9846,9858,10258,10280,10343,10586. RAN AIP, DENSITY, HGNS,NCT, SONIC FROM 10010-3947. TIGHT SPOT @ 9800'. STARTED CORING. RAN MSCT LOG. CUT DRILL LINE. WASH 120' TO BTM. DRILL 10586-10650 (NEW TD). CIRC & PUMP SWEEP. RAN PLATFORM EXPRESS. THREE DENSITY DETECTORS COMPENSATED NEUTRON FR 10641-3947. WASH 102' TO BTM. 6' FILL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *J. Denise Leake* TITLE Engineering Assistant DATE 10/16/00
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED
CONDITIONS OF APPROVAL IF ANY: TITLE DATE