DISTRICT I
------------

DISTRICT I	OIL CONSERVAT	TION I	DIVISION				
P. O. Box 1980, Hobbs, NM 88240				WELL API NO.			
	Santa Fe, New I	Mexico	86595	30-025	5-35257		
DISTRICT II				5. Indicat	e Type of Lease		_
P. O. Drawer DD, Artesia, NM 88210					STATE	FEE	X
DISTRICT III			ļ	C St-1: 0			
1000 Rio Brazos Rd., Aztec, NM 87410				o. State O	il & Gas Lease I	No.	
SUNDRY NOTICES AND REPORTS ON WELLS							
(DO NOT USE THIS FORM FOR PRO			LUG BACK TO	7. Lease Na	me or Unit Agre	ement Name	
DIFFERENT RESERV	VOIR. USE "APPLICATION FOR	R PERMIT					
1. Type of Well:	-101) FOR SUCH PROPOSALS)	<del></del>		Div. F	: 80.48		
Oil Gas				Diue F	in "24"		
Well X	OTHER						
2. Name of Operator				8. Well No.			<del></del> .
TMBR/Sharp Drilling, Inc.							
3. Address of Operator				1			
•				9. Pool nam	e or Wildcat		
P. O. Drawer 10970, Midland, TX	79702	<del> </del>		Towns	end; Mississ	ippian, N.	
4. Well Location							
Unit Letter M: 660	Feet From The We	st	Line and	760	Feet From The	South	
Section 24	Township 16S	D	255 2260		_		
	77777	Rang	ge 35E NMP! r DF, RKB, RT, GR, etc.)		County	Lea	,,,,,,,
	/////	964' GR					
11. Check Appr	copriate Box to Indicate			Other Dat			<u>//////</u>
NOTICE OF INTE	ENTION TO:				T REPORT (	OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		X ALTERI	ING CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING	G OPNS.	PLUG A	AND ABANDON	
PULL OR ALTER CASING			CASING TEST AND CE	MENT JOB			
OTHER:		П	OTHER:				П
12 Part 1							
<ol> <li>Describe Proposed or Completed Operations (Cl work) SEE RULE 1103.</li> </ol>	early state all pertinent details, an	id give perti	nent dates, including estimate	ed date of starti	ng any proposed		
00/44/00							
	up completion unit. Pump	57 BBL	10# brine down tbg.	Well on slig	ht vacuum. Ni	D wellhead	
and NU BOP. Try to	release packer. SDFN.			•	<b>)</b>		
03/15/02 SITP 300 psi. Ble	d wall down I and the w/	7 DDL 40	All bains Dillesson		J. W C	<i></i>	
SD for weather.	d well down. Load tbg w/7	/ BBL IC	# brine. RU power sw	/ivel and rel	ease packer.	RD swivel.	
ob for weather.				: 24	<b>K</b> V <b>L</b> OSS	`	
03/16/02 SITP 50 psi, SICP	0 psi. Pull tbg and packe	er. Pick i	in overshot GIH to 11	I,125'. <b>≲́</b> ⊅F	.M	'	
• *			ip o roronou. On reo r	ر الم	* .		
(Continued on attac	:hed page.)			**.		<i>://</i>	
I hereby certify that the information above is true and co	mplete to the best of my knowledge and	belief.				<del></del>	
SIGNATURE In line	TITLE	E	Production Manager	DA1	ne <u>04/17/0</u>	12	
TYPE OR PRINT NAME LONNIE Ar	nold			TEL	EPHONE NO.	(915) 699-505	0
(This space for State Use)							
APPROVED BY	-	_	ORIGINAL SIGNET		_ APR	1 9 2002	
	TITLE		PAUL F. KAUT	DAT			~
CONDITIONS OF APPROVAL, IF ANY:			PETROLEUM ENGI	MESIN			