Submit 3 Copies To Appropriate District Office	State of New M		Form C-103
District I	Energy, Minerals and Na	tural Resources	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240 District II	OH CONGERVATION DIVIGION		WELL API NO. 30-025-35369
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE
District IV	Santa Fe, NM	37505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			27147
	CES AND REPORTS ON WELL	S	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOS			
DIFFERENT RESERVOIR. USE "APPLIC. PROPOSALS.)	ATION FOR PERMIT" (FORM C-101)	OR SUCH	Bill's Hopper
1. Type of Well:			
	Z Other		
2. Name of Operator			7. Well No.
David H. Arrington Oil & Gas, Inc 3. Address of Operator	371 333 -		8. Pool name or Wildcat
P.O. Box 2071, Midland, Texas 797	03		Wildcat Mississippian
4. Well Location	03		windcat iviississippian
Unit LetterP:_	660'feet from theSouth	line and6	60'feet from theEastline
Section 18	Township 15S	Range 35E	NMPM Lea County
	10. Elevation (Show whether I 4025' GR	OR, RKB, RT, GR, etc	<i>:.)</i>
11 Check A	opropriate Box to Indicate N	Jature of Notice	Report or Other Data
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK		REMEDIAL WOR	
<u></u>			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS. 🗍 PLUG AND 🦳
			
, , , , , , , , , , , , , , , , , , ,	MULTIPLE	CASING TEST AN	ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AN	ABANDONMENT
PULL OR ALTER CASING		CEMENT JOB	ABANDONMENT LI
PULL OR ALTER CASING OTHER:	COMPLETION	OTHER: Comp	ABANDONMENT ABANDONMENT ABANDONMENT Lete Drig & Set Production Casing
PULL OR ALTER CASING OTHER: 12. Describe proposed or complete	COMPLETION d operations. (Clearly state all p	OTHER: Comp	ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT A
OTHER: 12. Describe proposed or complete of starting any proposed work).	COMPLETION d operations. (Clearly state all p	OTHER: Comp	ABANDONMENT ABANDONMENT ABANDONMENT Lete Drig & Set Production Casing
OTHER: 12. Describe proposed or complete	COMPLETION d operations. (Clearly state all p	OTHER: Comp	ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT A
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol	COMPLETION d operations. (Clearly state all p SEE RULE 1103. For Multiple	OTHER: Compertinent details, and good Completions: Attac	ABANDONMENT lete Drig & Set Production Casing give pertinent dates, including estimated date h wellbore diagram of proposed completion
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well.	COMPLETION d operations. (Clearly state all p SEE RULE 1103. For Multiple	OTHER: Compertinent details, and good Completions: Attac	ABANDONMENT lete Drig & Set Production Casing give pertinent dates, including estimated date h wellbore diagram of proposed completion
PULL OR ALTER CASING OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well.	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Res	OTHER: Compertinent details, and go Completions: Attack	ABANDONMENT Lete Drig & Set Production Casing Live pertinent dates, including estimated date h wellbore diagram of proposed completion 1/3/01.
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 ½	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Results are casing & set casing at 13,206'	OTHER: Compertinent details, and good Completions: Attacknowled TD 13,215', 11	ABANDONMENT Lete Drig & Set Production Casing Live pertinent dates, including estimated date h wellbore diagram of proposed completion 1/3/01.
PULL OR ALTER CASING OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 ½ 1st stage- Cement casing with the stage-	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Resulting to the 650 sxs Prem .6% Halad-9, .3	OTHER: Compertinent details, and grand ached TD 13,215', 11. Cement casing in 3% CFR-3, .2% Econo	ABANDONMENT lete Drig & Set Production Casing live pertinent dates, including estimated date h wellbore diagram of proposed completion /3/01. stages. blite, 4% HR-2.
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 1/1 stage- Cement casing with 2 stage-Cement casing with 2 stage-Cement casing with 2 stage-Cement casing with 2 stage-Cement casing with 3 stage-Cement casing w	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Results as to 650 sxs Prem .6% Halad-9, .3 th 820 sxs Prem .6% Halad-9, .3	CEMENT JOB OTHER: Comp ertinent details, and g Completions: Attac ached TD 13,215', 11 Cement casing in 3 CFR-3, .2% Econo CFR-3, .2% Econo CFR-3, .2% Econo	ABANDONMENT lete Drig & Set Production Casing live pertinent dates, including estimated date h wellbore diagram of proposed completion /3/01. stages. blite, 4% HR-2.
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 to 1 stage-Cement casing with 2 stage-Cement casing with 3 stage-Cement casing w	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Resulting to the 650 sxs Prem .6% Halad-9, .3	CEMENT JOB OTHER: Comp ertinent details, and g Completions: Attac ached TD 13,215', 11 Cement casing in 3 CFR-3, .2% Econo CFR-3, .2% Econo 21% CFR-3, .2% Econo 21% CaCl2.	ABANDONMENT lete Drig & Set Production Casing live pertinent dates, including estimated date h wellbore diagram of proposed completion /3/01. stages. blite, .4% HR-7. blite, .2% HR-7.
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 to 1 stage-Cement casing with 2 stage-Cement casing with 3 stage-Cement casing w	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Results as a set casing at 13,206' th 650 sxs Prem .6% Halad-9, .3 th 820 sxs Prem .6% Halad-9, .3 th 700 sxs Prem Plus 5# Gilsonit	CEMENT JOB OTHER: Comp ertinent details, and g Completions: Attac ached TD 13,215', 11 Cement casing in 3 CFR-3, .2% Econo CFR-3, .2% Econo 21% CFR-3, .2% Econo 21% CaCl2.	ABANDONMENT lete Drig & Set Production Casing live pertinent dates, including estimated date h wellbore diagram of proposed completion /3/01. stages. blite, .4% HR-7. blite, .2% HR-7.
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 to 1 stage-Cement casing with 2 stage-Cement casing with 3 stage-Cement casing w	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Results as a set casing at 13,206' th 650 sxs Prem .6% Halad-9, .3 th 820 sxs Prem .6% Halad-9, .3 th 700 sxs Prem Plus 5# Gilsonit	CEMENT JOB OTHER: Comp ertinent details, and g Completions: Attac ached TD 13,215', 11 Cement casing in 3 CFR-3, .2% Econo CFR-3, .2% Econo 21% CFR-3, .2% Econo 21% CaCl2.	ABANDONMENT lete Drig & Set Production Casing live pertinent dates, including estimated date h wellbore diagram of proposed completion /3/01. stages. blite, .4% HR-7. blite, .2% HR-7.
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 to 1 stage-Cement casing with 2 stage-Cement casing with 3 stage-Cement casing w	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Results as a set casing at 13,206' th 650 sxs Prem .6% Halad-9, .3 th 820 sxs Prem .6% Halad-9, .3 th 700 sxs Prem Plus 5# Gilsonit	CEMENT JOB OTHER: Comp ertinent details, and g Completions: Attac ached TD 13,215', 11 Cement casing in 3 CFR-3, .2% Econo CFR-3, .2% Econo 21% CFR-3, .2% Econo 21% CaCl2.	ABANDONMENT lete Drig & Set Production Casing live pertinent dates, including estimated date h wellbore diagram of proposed completion /3/01. stages. blite, .4% HR-7. blite, .2% HR-7.
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 ! 1st stage- Cement casing with 2nd stage-Cement casing with 3rd stage-Cement casing with Circ 5 sxs to pit. ND & set	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Research to 650 sxs Prem .6% Halad-9, .3 th 820 sxs Prem .6% Halad-9, .3 th 700 sxs Prem Plus 5# Gilsonit slips. Jet & clean pits. Released	CEMENT JOB OTHER: Comp ertinent details, and g Completions: Attac ached TD 13,215', 11 Cement casing in 3 CFR-3, .2% Econo CFR-3, .2% Econo 1% CFR-3, .2% Econo 11% CaCl2. 1 rig 11/7/01.	ABANDONMENT Lete Drig & Set Production Casing Live pertinent dates, including estimated date h wellbore diagram of proposed completion /3/01. stages. blite, .2% HR 3. LE OE 6. LE OE
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 to 1 stage-Cement casing with 2 stage-Cement casing with 3 stage-Cement casing w	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Research to 650 sxs Prem .6% Halad-9, .3 th 820 sxs Prem .6% Halad-9, .3 th 700 sxs Prem Plus 5# Gilsonit slips. Jet & clean pits. Released	CEMENT JOB OTHER: Comp ertinent details, and g Completions: Attac ached TD 13,215', 11 Cement casing in 3 CFR-3, .2% Econo CFR-3, .2% Econo 1% CFR-3, .2% Econo 11% CaCl2. 1 rig 11/7/01.	ABANDONMENT Lete Drig & Set Production Casing Live pertinent dates, including estimated date h wellbore diagram of proposed completion /3/01. stages. blite, .2% HR 3. LE OE 6. LE OE
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 ! 1st stage- Cement casing with 2nd stage-Cement casing with 3rd stage-Cement casing with Circ 5 sxs to pit. ND & set	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Research to 650 sxs Prem .6% Halad-9, .3 th 820 sxs Prem .6% Halad-9, .3 th 700 sxs Prem Plus 5# Gilsonit slips. Jet & clean pits. Released	CEMENT JOB OTHER: Comp ertinent details, and g Completions: Attac ached TD 13,215', 11 Cement casing in 3 CFR-3, .2% Econo CFR-3, .2% Econo 1% CFR-3, .2% Econo 11% CaCl2. 1 rig 11/7/01.	ABANDONMENT Lete Drig & Set Production Casing Live pertinent dates, including estimated date h wellbore diagram of proposed completion 1/3/01. Stages. Ditte, .4% HR-7. Ditte, .2% HR-7. LEDE 62. LEDE 62. LEDE 62. LEDE 64. LED
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 ½ 1st stage- Cement casing with 2nd stage-Cement casing with 3rd stage-Cement casing with Circ 5 sxs to pit. ND & set	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Research to 650 sxs Prem .6% Halad-9, .3 th 820 sxs Prem .6% Halad-9, .3 th 700 sxs Prem Plus 5# Gilsonit slips. Jet & clean pits. Released	CEMENT JOB OTHER: Comp ertinent details, and g Completions: Attac ached TD 13,215', 11 Cement casing in 3 CFR-3, .2% Econo CFR-3, .2% Econo 11 CaCl2. 1 rig 11/7/01.	ABANDONMENT State Drig & Set Production Casing Drive pertinent dates, including estimated date in wellbore diagram of proposed completion 13/01. Stages. Drive Drive
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 ! 1st stage- Cement casing with 2nd stage-Cement casing with 3rd stage-Cement casing with Circ 5 sxs to pit. ND & set I hereby certify that the information SIGNATURE Type or print name Chuck Sledge	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Research to 650 sxs Prem .6% Halad-9, .3 th 820 sxs Prem .6% Halad-9, .3 th 700 sxs Prem Plus 5# Gilsonit slips. Jet & clean pits. Released	CEMENT JOB OTHER: Comp ertinent details, and g Completions: Attac ached TD 13,215', 11 Cement casing in 3 CFR-3, .2% Econo CFR-3, .2% Econo 11 CaCl2. 1 rig 11/7/01.	ABANDONMENT Lete Drig & Set Production Casing Live pertinent dates, including estimated date h wellbore diagram of proposed completion 1/3/01. Stages. Ditte, .4% HR-7. Ditte, .2% HR-7. LEDE 62. LEDE 62. LEDE 62. LEDE 64. LED
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 ½ 1st stage- Cement casing with 2nd stage-Cement casing with 3rd stage-Cement casing with Circ 5 sxs to pit. ND & set	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Research to 650 sxs Prem .6% Halad-9, .3 th 820 sxs Prem .6% Halad-9, .3 th 700 sxs Prem Plus 5# Gilsonit slips. Jet & clean pits. Released	CEMENT JOB OTHER: Comp ertinent details, and g Completions: Attac ached TD 13,215', 11 Cement casing in 3 CFR-3, .2% Econo CFR-3, .2% Econo 11 CaCl2. 1 rig 11/7/01.	ABANDONMENT State Drig & Set Production Casing Drive pertinent dates, including estimated date in wellbore diagram of proposed completion 13/01. Stages. Drive Drive
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 the stage-Cement casing with 2nd stage-Cement casing with 3rd stage-Cement casing with Circ 5 sxs to pit. ND & set of the stage of t	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Research casing & set casing at 13,206' th 650 sxs Prem .6% Halad-9, .3 th 820 sxs Prem .6% Halad-9, .3 th 700 sxs Prem Plus 5# Gilsonit slips. Jet & clean pits. Released	CEMENT JOB OTHER: Comp ertinent details, and g Completions: Attac ached TD 13,215', 11 Cement casing in 3 CFR-3, .2% Econo CFR-3, .2% Econo 11 CaCl2. 1 rig 11/7/01.	ABANDONMENT State Drig & Set Production Casing Drive pertinent dates, including estimated date in wellbore diagram of proposed completion 13/01. Stages. Drive Drive
OTHER: 12. Describe proposed or complete of starting any proposed work). or recompilation. 10/2/01- 11/3/01- Drilled 7 7/8" hol 11/4/01- Prep to log well. 11/5/01- Log well. 11/6/01- Circ to run casing. Ran 5 ! 1st stage- Cement casing with 2nd stage-Cement casing with 3rd stage-Cement casing with Circ 5 sxs to pit. ND & set I hereby certify that the information SIGNATURE Type or print name Chuck Sledge	d operations. (Clearly state all p SEE RULE 1103. For Multiple e from 4735' to TD 13,215'. Research to 650 sxs Prem .6% Halad-9, .3 th 820 sxs Prem .6% Halad-9, .3 th 700 sxs Prem Plus 5# Gilsonit slips. Jet & clean pits. Released	CEMENT JOB OTHER: Comp ertinent details, and g Completions: Attac ached TD 13,215', 11 Cement casing in 3 CFR-3, .2% Econo CFR-3, .2% Econo 11 CaCl2. 1 rig 11/7/01.	ABANDONMENT Stages. S