

**DISTRICT I**

P. O. Box 1980, Hobbs, NM 88240

**OIL CONSERVATION DIVISION**

2040 South Pacheco  
Santa Fe, New Mexico 86595

**DISTRICT II**

P. O. Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.  
**30-025-35865**

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT  
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:  
Oil Well ☐ Gas Well ☒ OTHER

2. Name of Operator  
**TMBR/Sharp Drilling, Inc.**

3. Address of Operator  
**P. O. Drawer 10970, Midland, TX 79702**

4. Well Location  
Unit Letter **E** : **1913** Feet From The **North** Line and **924** Feet From The **West**  
Section **25** Township **16S** Range **35E** NMPM County **Lea**

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
**GR 3959'**

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐  
CASING TEST AND CEMENT JOB ☒  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

06/26/02 Reached TD of 13,200'. Lay down drill pipe and collars.

06/27/02 Ran 299 jts 5-1/2" 17# LT&C S-95 & N-80 casing and set @ 13,200'. DV tool @ 8808'. Cement 1st stage with 415 sx 35/65 Poz "H" w/.3% CD-32 + .3% FL-25 + .1% SMS + .1% R-21 + 1/4# CF/sx + 1070 sx CI "H" with .2% LD-32 + 1% FL-62 + .1% SMS. Plug down @ 3:30 PM 06/27/02. Open DV tool. Circulated out an estimated 68 sx cement. Circulated 4 hrs. Cement 2nd stage as follows: 925 sx 35/65 Poz "H" cement and 150 sx CI "H" Neat. Plug down @ 8:45 PM. Close DV tool and rig down BOP. Set slips and nipple up wellhead. Released rig @ 6:00 AM 06/28/02.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Lonnie Arnold*

TITLE

**Production Manager**

DATE

**July 10, 2002**

TYPE OR PRINT NAME

**Lonnie Arnold**

TELEPHONE NO.

**(915) 699-5050**

(This space for State Use)

APPROVED BY

TITLE

ORIGINAL SIGNED BY  
**PAUL F. KAUTZ**  
PETROLEUM ENGINEER

DATE

**JUL 16 2002**

CONDITIONS OF APPROVAL, IF ANY: