x	-	

## (SUBMIT IN TRIPLICATE)

Land Office	lev	Hexico
Lease No	LC-(	065007-B
Unit	<b></b>	

## DEPARTMENT OF THE INTERIOR

## SUNDRY NOTICES AND REPORTS ON WELLS

VACUUS OF INTENTION TO DOU'	<b>≭</b> SUB	SEQUENT REPORT OF WATER SHUT-OFF	1
NOTICE OF INTENTION TO DRILL		SEQUENT REPORT OF SHOOTING OR ACIDIZING	l i
NOTICE OF INTENTION TO CHANGE PLANS		SEQUENT REPORT OF ALTERING CASING	1 1
NOTICE OF INTENTION TO TEST WATER SHUT-OF	1 1	SEQUENT REPORT OF RE-DRILLING OR REPAIR.	i i
NOTICE OF INTENTION TO RE-DRILL OR REPAIR		SEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		PLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO PULL OR ALTER CASIN		-LEMENTARY WELL MISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
(INDICATE ABOVE B	Y CHECK MARK NATURE O	F REPORT, NOTICE, OR OTHER DATA)	
		Narch 4	, 19. <b>57</b> .
Federal QA Vell No. 1 is located 660	ft from $\{N\}$	ine and 1980 ft. from	of sec <b>28</b>
eli ivo, is located 1990	***	,	
NR 4 NV 4 Sec. 28 18 (3/4 Sec. and Sec. No.)	wp.) 32- (Range)	(Meridian)	
Undesignated (Field)	County or Subdivis	on) Rey Mexico (State or Territory	)
he elevation of the derrick floor ak	oove sea level is	3760 ft. estimated	
	DETAILS OF	WORK	
tate names of and expected depths to objective a ing p	sands; show sizes, weight points, and all other impo	s, and lengths of proposed casings; indicate mu rtant proposed work)	dding jobs, cement-
tate names of and expected depths to objective ing p	sands; show sizes, weight soints, and all other impo		dding jobs, cement-
			dding jobs, cement-
BJECTIVE FORMATION:	Penrose 4150		
BJECTIVE FORMATION: BJECTIVE TOTAL DEPTH:	Penrose 4150	41001.	
BJECTIVE FORMATION: BJECTIVE TOTAL DEPTH:	Penrose 4150	41001.	
BJECTIVE FORMATION: BJECTIVE TOTAL DEPTH: ASING PROGRAM:	Penrose 4150' 8 5/8*, 5 1/2*,	4100'. 32#, @ 750' w/900 ex. (Cir 15.5# @ 4100' w/800 ex.	culate to surfac
BJECTIVE FORMATION:  BJECTIVE TOTAL DEPTH:  ASING PROGRAM:  I understand that this plan of work must reco	Penrose  4150!  8 5/8*.  5 1/2*,	4100'.  32#, @ 750' w/900 sx. (Cir 15.5# @ 4100' w/800 sx.	culate to surfac
BJECTIVE FORMATION: BJECTIVE TOTAL DEPTH: ASING PROGRAM:	Penrose  4150!  8 5/8*.  5 1/2*,	4100'.  32#, @ 750' w/900 sx. (Cir 15.5# @ 4100' w/800 sx.	culate to surfac
BJECTIVE FORMATION:  BJECTIVE TOTAL DEPTH:  ASING PROGRAM:  I understand that this plan of work must recompany Shell Oil Cor	Penrose  4150  8 5/8*. 5 1/2*.	4100'.  32#, @ 750' w/900 sx. (Cir 15.5# @ 4100' w/800 sx.	culate to surface
BJECTIVE FORMATION:  BJECTIVE TOTAL DEPTH:  ASING PROGRAM:  I understand that this plan of work must reco	Penrose  4150  8 5/8*. 5 1/2*.	4100'.  32#, @ 750' w/900 sx. (Cir 15.5# @ 4100' w/800 sx.	culate to surface

