

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-062391

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Wyatt B-Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Corbin Abo

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 33-T17S-R33E

12. COUNTY OR PARISH

Lee

13. STATE

N.Mex.

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

CITIES SERVICE OIL COMPANY

3. ADDRESS OF OPERATOR

P.O. Box 60, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990' FSL & 330' FEL of sec. 33-T17S-R33E, Lee County, N.M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4109 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) **Perf Additional Abo zone** ☒

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 8850, PSTD 8800 Workover complete. Well was pumping 36 BO + 97 BWPH * Respu 12-6-71. Pulled rods and tubing. Perforated w/1 - 3/8" hole each @ 8617, 8619, 8621, 8635, 8645, 8653, 8661, 8663, 8670, 8677, 8684, 8689, 8693, 8696 & 8698. Ran and set a RSP @ 8705 W/ RTTS tool @ 8563. Swabbed 18 BO + 31 BW/4 hrs. Shut well in for 12 hrs. Swabbed 21 BO + 33 BW/4 hrs. thru new perfs (8617--8698). Pulled RSP & RTTS tool. Ran and set 2 3/8" tubing @ 8653. Ran rods and pump. Pumped on repotential 55 BO + 90 BW/24 hrs, thru all perfs (8617-8698 & 8734-8764) GOR 1390 Grav. 38.7 API @ 60°. Well recompleted on 12-13-71.

*** Thru old perfs 8734-8764.**

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE **Dist. Admin. Supervisor**

DATE **Dec. 15, 1971**

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED FOR RECORD
DATE 12-16-71

DEC 16 1971

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; and other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the device to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963 O - 685229
807 - 485

RECEIVED

DEC 21 1971

OIL CONSERVATION COMM.

HOOD, R. M.