

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
P.O. Box 1980
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.
NMLC062391

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

SUBMIT IN TRIPLICATE

1. Type of Well
 Oil Well Gas Well Other

8. Well Name and No. *5675*
Wyatt A Federal #1

2. Name of Operator
OXY USA Inc. *16696*

9. API Well No.
30-025-01384

3. Address and Telephone No.
P.O. Box 50250 Midland, TX 79710-0250 915-685-5717

10. Field and Pool, or Exploratory Area
Corbin Queen 13280

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
660 FSL 660 FEL SESE (P) Sec 33 T17S R33E

11. County or Parish, State
Lea NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

TD - 7042' PBDT - 4095' OH - 4045-4095'

NOTIFY BLM OF P&A 4/17/96. REMOVE PU BASE, DIG OUT CELLAR, BREAK OUT FLOWLINE, LEVEL LOCATION, DIG WO PIT. MIRU PU 4/18/96, ND WH, NU BOP. POOH W/ TBG, RIH W/ CIBP & SET @ 4000'. CIRC HOLE W/ MUD-LADEN FLUID, SPOT 10sx(50') CL C CMT PLUG ON CIBP. POOH TO 2850'. SPOT 25sx CL C CMT PLUG @ 2850-2750', POOH, WOC 4hrs. RIH TO TAG PLUG, PLUG WAS NOT THERE, SPOT 65sx CL C CMT PLUG @ 2850', POOH, DANNY CORTEZ W/ BLM WITNESSED PLUG, SION. RIH & TAG PLUG @ 2587', POOH. RIH W/ WL & PERF 4 SQZ HOLES @ 1598', RIH & SET CR @ 1562', EIR @ 2BPM @ 1200#, M&P 200sx CL C CMT, CIRC CMT TO SURFACE, DUMP 100' ON TOP OF CR, POOH, SION. SPOT 13sx CL C CMT PLUG TO SURF, BLM NOTIFIED, BUT DID NOT WITNESS. NDBOP, RDPU-4/23/96, CUTOFF WH, BACKFILL ALL PITS, INSTALL DH MARKER, LEVEL & CLEAN LOCATION.

Approved as to plugging of this well done
Use of well for other purposes until

14. I hereby certify that the foregoing is true and correct
Signed *[Signature]* Title *David Stewart* Date *4/10/97*
Regulatory Analyst

(This space for Federal or State office use)
Approved by *(ORIG. SGD.) ALEXIS C SWOBODA* Title *PETROLEUM ENGINEER* Date *APR 15 1997*
Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.