ENERGY AND MINERALS DEPARTMENT


me. er carica acctives	<u> </u>	
DISTRIBUTION		
SANTA PE		
FILE		
V.S.G.S.		
LAND OFFICE		
0000000	i	i

OF CONSERVATION DIVIS' N

ne. or conice acceives	P. O. BOX	2098	Form C-103
DISTRIBUTION			Revised 10-1-73
SANTA PE	SANTA FE, NEW I	MEXICO 8/501	Sa. Indicate Type of Lease
FILE			[]
U.S.O.S.			State X Fee
LAND OFFICE			5. State Oil & Gas Lease No.
OPERATOR	1		B-2229
			THITTINITY OF THE STATE OF THE
SUNDR	Y NOTICES AND REPORTS ON Y	VELLS	
(06 HOT USE THIS FORM FOR PRO USE "APPLICAT"	POSALS TO DRILL OR TO DEEPEN OF PLUG BEING FOR BUCH	PROPOSALS.)	7, Unit Agreement Name
1.			7. Unit Adreement None
	OTHER-		
OIL X WELL WELL			8. Form or Lease Name
Name of Operator ARCO Oil and Gas Company		State "F" TG	
Division of Atlantic Richfield Company		9. Well No.	
3. Address of Operator			2
P.O. Box 1710, Hobbs, New Mexico 88240		10. Field and Pool, or Wildcat	
1 1 organism of Well			
	660 FEET FROM THE East	LINE AND 1980 FEET FRO	Vacuum Grbg SA
UNIT LETTER H	PEET PROM THE		
_	26 179	names 33E	
THE North LINE, SECTI	ON 36 TOWNSHIP 175	RANGE	<u>(</u>
	15. Elevation (Show whether i	DF RT. GR. etc.)	12. County
	((((((((((((((((((((, , , , , , , , , , , , , , , , , , ,	Lea (IIIIIIIII
	4111' TH		
16. Check	Appropriate Box To Indicate N	ature of Notice, Report or C	Other Data
	NTENTION TO:	SUBSEQUE	NT REPORT OF:
NOTICE OF I	NIENTION 10.		
	PLUG AND ABANDON		ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON		PLUG AND ABANDONMENT
TEMPORARILY ASANDON	<u> </u>	COMMENCE DRILLING OPHS.	
PULL OR ALTER CABING	CHANGE PLANS	CASING TEST AND CEMENT JOS	
-		OTHER	
F	Repair Casing X		
OTHER			in actimated date of starting any proposed
17. Describe Proposed or Completed C	Operations (Clearly state all pertinent det	ails, and give pertinent dates, includ	ing estimated date of starting any proposed
work) SEE RULE 1103.			
	rods & pump. Install BOP &	POH w/comp assy.	
1. Rig up, Fon w/	', pkr @ various intervals	& locate holes in cas	ing,
establish pump	on rate. bove holes in casing and o	omt squeeze w/amt & kin	d of cmt.
Set cmt retr a	bove holes in casing and o	nut 11 out 5 proceure te	est squeeze
	1 1 in rota Will.	III III DUL U DICOCULC CO	
1000# E	ar 20 mine Re-squeeze 11	necessary, rress cose	546661
/ POH w/RRP RIH	w/comp assy, rods & pump	& return to production	1.
4. 1011 W/REF. 1123-			
		•	
•	÷		
		÷	
•		44-11-4	
the informat	ion above is true and complete to the best	of my knowledge and belief.	•

DATE 7/25/85 Engrg. Tech. Spec. 147 M22

RECEIVED JUL 26 1985



ARCO Oil & Gas Company
Division of Atlantic Richfield Company

Blow Out Preventer Program

Lease 'Name_	State "F" TG
Well No.	2
Location	660' FEL & 1980' FNL
	Sec 36-17S-33E. Lea County

BOP to be tested when installed on well and will be maintained in good working condition during drilling. All wellhead fittings to be of sufficient pressure to operate in a safe manner.

JUL 26 1985