

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-01426
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other SWD		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Phillips Petroleum Company		6. State Oil & Gas Lease No. B-2229
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762		7. Lease Name or Unit Agreement Name: STATE E&F TG SWD
4. Well Location Unit Letter A : 660 feet from the EAST line and 990 feet from the NORTH line Section 36 Township 17S Range 33E NMPM County LEA		8. Well No. D05
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4105' GR		9. Pool name or Wildcat VACUUM GRAYBURG/SAN ANDRES

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: C/O, TEST & REQUEST T.A. STATUS <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

10/17/01 RU DDU ND WH NU BOP TRIED T/UNSEAT PACKER.
10/18/01 UNSEAT PKR COOH W/TBG, AD1 PKR GIH W/5-1/2 BIT, SCRAPER, BIT @ 4525' COOH W/TBG/BIT/SCRAPER
10/19/01 GIH W/CIBP T/4517' CIRC HOLE W/100 EBL PKR FL PSI TST CSG/CIBP T/500 F/30 MIN (CHART ATTACHED)
OK COOH W/TBG LD 146 JTS 2-3/8 RICE DOULINE TBG ND BOP NU WH RD DDU WELL T/A - DROP F/REPORT.

This Approval of Temporary
Abandonment Expires 11/5/06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE SUPVR., REGULATION/PRODUCTION DATE 10/26/01
Type or print name **LARRY M. SANDERS** Telephone No. **915/368-1488**

APPROVED BY [Signature] TITLE ORIGINAL SIGNED BY DATE NOV 06 2001
Conditions of approval, if any: **GARY W. WINK**
NATURAL SCIENCE MANAGER - 2

STFTG #5

MIT

Start 520

Finish 515

Pulling Unit was used on this well

Well Status T/A.

CIBP @ 4517'