

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-2229

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name --
2. Name of Operator PENNZOIL COMPANY	8. Farm or Lease Name Phillips State
3. Address of Operator P.O. Drawer 1828, Midland, Texas	9. Well No. 12
4. Location of Well UNIT LETTER <u>I</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>17-S</u> RANGE <u>33-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Maljamar GB-SA
15. Elevation (Show whether DF, RT, GR, etc.) 4190 KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/1/80 - 7/3/80
Estimated Date
RU pulling unit. POH w/tbg & rods. GIH w/5-1/2" pkr & plug on 2-3/8" tbg. Treat Grayburg in 2 equal states. using a total of 6000 gals 15% iron stabilized acid. POH w/pkr & plug. Place well back on pump to recover load & test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. V. Sullivan</u>	TITLE <u>Operations Engineer</u>	DATE <u>June 2, 1980</u>
Orig. Signed by APPROVED BY <u>Jerry Sexton</u>	TITLE <u>Dist. 1, Supv.</u>	DATE <u>JUN 4 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		