rm 3160-5	L . FD S	TATES	ico Oil Conservation 1625 N. ten d	FORM APPROVED Budget Bureau No. 1004-0135 Evolution: March 21, 1003
ine 1990)	DEPARTMENT OF BUREAU OF LAND	THE INTERIOR	Hothy MAR In	Expires: March 31, 1993 5. Lease Designation and Serial No.
	SUNDRY NOTICES AND	REPORTS ON WELL	S	6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals				b. If filling, Anotee of those value
	SUBMIT IN TI	RIPLICATE		7. If Unit or CA, Agreement Designation
Type of Well Oil Gas Well Well	Other			8. Well Name and No.
2. Name of Operator Saga Petroleum LLC 3. Address and Telephone No.			Wyatt "A" Fed #6	
			30-025-01581	
415 W. Wall, Suite 1900, Midland, TX. 79701				10. Field and Pool, or Exploratory Area
4. Location Well (Footage, Sec., T., R., M., or Survey Description) 1980' FL & 660' FWL Sec 5 (E) T 18S R 33E				Corbin Queen 11. County or Parish, State
				Lea, NM
	PROPRIATE BOX(s) TO	NDICATE NATURE (OF NOTICE, REPORT, C	OR OTHER DATA
	UBMISSION	X Abandonmen		Change of Plans
Notice of In	ntent	Recompletion		New Construction
X Subsequer	nt Report	Plugging Bacl		Non-Routine Fracturing
		Casing Repai	r	Water Shut-Off
Final Abandonment Notice		Altering Casir	ŋg	Conversion to Injection Dispose Water
		Other		Dispose vvaler
directionally drilled, give s 1. 11/21/01Tag BP an 2. 11/26/01 Perf. 5 1/2 neat cmt. 3. 11/27/01 Cut & PO 1. 11/20/01 Tagged	ubsurface locations and measured and nd spot 20 sx. class "C" neat of 2 csg. @ 2550. Pressured up @ 2606. WOC 4 hrs. Tagged H 1510' of 5 1/2 csg. Spot 10	and the ventical depuision and the emt. @ 3989 to 3791. to 1800 psi. Received ap d plug @2292. 0 sx. class "C" neat cmt @ 350' Soz 110 sx. cla	oproval from David Glass an . @ 1570 '. Shut in for nite.	d spot 40 sx. class "C" er nite.
directionally drilled, give s 1. 11/21/01Tag BP an 2. 11/26/01 Perf. 5 1/2 neat cmt. 3. 11/27/01 Cut & PO 4. 11/29/01 Tagged p 5. 11/30/01 Tagged p	ubsurface locations and measured and nd spot 20 sx. class "C" neat c 2 csg. @ 2550. Pressured up @ 2606. WOC 4 hrs. Tagger IH 1510' of 5 1/2 csg. Spot 10	Approved 8	oproval from David Glass an . @ 1570 '. Shut in for nite. ss "C" neat cmt. Shut in ove C" neat cmt. down 8 5/8 cxg	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* d spot 40 sx. class "C"
directionally drilled, give s 1. 11/21/01Tag BP an 2. 11/26/01 Perf. 5 1/2 neat cmt. 3. 11/27/01 Cut & PO 4. 11/29/01 Tagged p 5. 11/30/01 Tagged p	ubsurface locations and measured and nd spot 20 sx. class "C" neat of 2 csg. @ 2550. Pressured up @ 2606. WOC 4 hrs. Tagged H 1510' of 5 1/2 csg. Spot 10 lug @ 1304'. Perf. 8 5/8 csg. lug @ 244'. Perf 8 5/8 csg. @	Approved 8	oproval from David Glass an . @ 1570 '. Shut in for nite. ss "C" neat cmt. Shut in ove C" neat cmt. down 8 5/8 cxg	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* d spot 40 sx. class "C"
directionally drilled, give s 1. 11/21/01Tag BP an 2. 11/26/01 Perf. 5 1/2 neat cmt. 3. 11/27/01 Cut & PO 4. 11/29/01 Tagged p 5. 11/30/01 Tagged p	ubsurface locations and measured and nd spot 20 sx. class "C" neat of 2 csg. @ 2550. Pressured up @ 2606. WOC 4 hrs. Tagged H 1510' of 5 1/2 csg. Spot 10 lug @ 1304'. Perf. 8 5/8 csg. lug @ 244'. Perf 8 5/8 csg. @	Approved 8	oproval from David Glass an . @ 1570 '. Shut in for nite. ss "C" neat cmt. Shut in ove C" neat cmt. down 8 5/8 cxg	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* d spot 40 sx. class "C"
directionally drilled, give s 1. 11/21/01Tag BP an 2. 11/26/01 Perf. 5 1/2 neat cmt. 3. 11/27/01 Cut & PO 4. 11/29/01 Tagged p 5. 11/30/01 Tagged p Cut off v	ubsurface locations and measured and ad spot 20 sx. class "C" neat of 2 csg. @ 2550. Pressured up @ 2606. WOC 4 hrs. Tagged H 1510' of 5 1/2 csg. Spot 10 lug @ 1304'. Perf. 8 5/8 csg. lug @ 244'. Perf 8 5/8 csg. @ vell head & install Dry Hole Ma	Approved a Approved a Listing of the Approved a Approved Approved a Approved a Approved	oproval from David Glass an . @ 1570 '. Shut in for nite. ss "C" neat cmt. Shut in ove C" neat cmt. down 8 5/8 cxg	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* d spot 40 sx. class "C" or nite. & up to surface on backside.
directionally drilled, give s 1. 11/21/01Tag BP an 2. 11/26/01 Perf. 5 1/2 neat cmt. 3. 11/27/01 Cut & PO 4. 11/29/01 Tagged p 5. 11/30/01 Tagged p Cut off v 14. I hereby certify that the for Signed	ubsurface locations and measured and ad spot 20 sx. class "C" neat of 2 csg. @ 2550. Pressured up @ 2606. WOC 4 hrs. Tagged H 1510' of 5 1/2 csg. Spot 10 lug @ 1304'. Perf. 8 5/8 csg. lug @ 244'. Perf 8 5/8 csg. @ vell head & install Dry Hole Ma	Approved 8	oproval from David Glass an . @ 1570 '. Shut in for nite. ss "C" neat cmt. Shut in ove C" neat cmt. down 8 5/8 cxg	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* d spot 40 sx. class "C" er nite. & up to surface on backside.
directionally drilled, give s 1. 11/21/01Tag BP an 2. 11/26/01 Perf. 5 1/2 neat cmt. 3. 11/27/01 Cut & PO 4. 11/29/01 Tagged p 5. 11/30/01 Tagged p Cut off v 14. I hereby certify that the form	ubsurface locations and measured and ad spot 20 sx. class "C" neat of 2 csg. @ 2550. Pressured up @ 2606. WOC 4 hrs. Tagged H 1510' of 5 1/2 csg. Spot 10 lug @ 1304'. Perf. 8 5/8 csg. lug @ 244'. Perf 8 5/8 csg. @ vell head & install Dry Hole Ma	Approved a Approved a Listing of the Approved a Approved Approved a Approved a Approved	oproval from David Glass an . @ 1570 '. Shut in for nite. ss "C" neat cmt. Shut in ove C" neat cmt. down 8 5/8 cxg	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* d spot 40 sx. class "C" or nite. & up to surface on backside.
directionally drilled, give s 1. 11/21/01Tag BP an 2. 11/26/01 Perf. 5 1/2 neat cmt. 3. 11/27/01 Cut & PO 4. 11/29/01 Tagged p 5. 11/30/01 Tagged p Cut off v 14. I hereby certify that the for Signed Conditions of approvel of the performance of the per	oregoing is true and correct O . Succession of the second	Title Cementer	pproval from David Glass an . @ 1570 '. Shut in for nite. ss "C" neat cmt. Shut in ove C" neat cmt. down 8 5/8 cxg	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* d spot 40 sx. class "C" or nite. & up to surface on backside.
directionally drilled, give s 1. 11/21/01Tag BP an 2. 11/26/01 Perf. 5 1/2 neat cmt. 3. 11/27/01 Cut & PO 4. 11/29/01 Tagged p 5. 11/30/01 Tagged p 5. 11/30/01 Tagged p Cut off v 14. I hereby certify that the form Signed Construction of approved by Conditions of approved of the provention of approved by DEC Title 18 U.S.C. Section 1001 statements or representation	oregoing is true and correct O Suchas it a crime for any person kno to as to any matter within its jurgdicti	Title Title	any department or agency of the U	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* d spot 40 sx. class "C" or nite. & up to surface on backside.
directionally drilled, give s 1. 11/21/01Tag BP an 2. 11/26/01 Perf. 5 1/2 neat cmt. 3. 11/27/01 Cut & PO 4. 11/29/01 Tagged p 5. 11/30/01 Tagged p 5. 11/30/01 Tagged p Cut off v 14. I hereby certify that the form Signed Construction of approved by Conditions of approved of the provention of approved by DEC Title 18 U.S.C. Section 1001 statements or representation	oregoing is true and correct O. Sacchas DAVID FL. C. ASS C. 6 2001 I, makes it a crime for any person known I as as to any matter within its jursdiction	Title Cementer Title Title	any department or agency of the U	Completion or Recompletion Report and Log form.) of starting any proposed work. If well is work.)* d spot 40 sx. class "C" or nite. & up to surface on backside.

