

U. S. OIL CONS. COMMISSION

P. O. BOX 1980

ROSWELL, NEW MEXICO 88240

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐

2. NAME OF OPERATOR
Mobil Producing TX. & N.M. Inc.

3. ADDRESS OF OPERATOR Nine Greenway Plaza,
Suite 2700, Houston, Texas 77046

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 660' FSL & 660' FEL
AT TOP PROD. INTERVAL: Same as surface
AT TOTAL DEPTH: Same as surface

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) PLUG BACK ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE

LC-063645

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Carper-Sivley Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

E-K Yates 7-Rivers Queen

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 13, T18S, R33E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
DF 3975, KB 3976, GR 3966

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 4405, PBTD 4280

07/27/83 MIRU DA&S WS Ut, NU BOP, unload & rack 145 jts 2-3/8 tbg, WIH w/ 7" HOWCO cmt ret on 2-3/8 tbg, pump thru ret, set ret @ 4295, attm to press 7" csg, PI 3 BPM @ 400 psi, ISIP 400 & holding, pump down tbg into Queen OHZ 4375-4405 2 BPM @ 2300, csg holding 400 ok, HOWCO cmtd Queen OHZ w/ 50x Class C cmt, sqz press 2000, pull out of ret, rev circ out 6x cmt, leaving 15' cmt on top of ret = 4280 PBTD, notified Glinda Littlefield w/ NM OCD, Hobbs office, job not witnessed, displ 7" csg w/ 180 bbls 10# br wtr, POH w/ ret stinger.

07/28/83 Schl ran CCL 4318-2290, Thermal Decay Time Log 4318-2290 corr to Welx Radio-activity Log 9/25/68, ran CET Log 4318-2290, ind good cmt 4318-3400, 3400 to surf showed free csg, job compl @ 3 pm 7/28/83.

07/29/83 WIH w/ 7" CS on 2-3/8 tbg to 4280, circ hole clean, POH w/ scpr, WIH w/ -SEE REVERSE-

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Paula A. Collins TITLE Authorized Agent DATE August 30, 1983

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL IF ANY:

TITLE _____

DATE _____

ACCEPTED FOR RECORD

SEP - 8 1983

*See Instructions on Reverse Side

ROSWELL, NEW MEXICO

#17 continued from front

07/29/83 Arrow 7" ten pkr on 2-3/8 tbg, loc 7" csg leak 2523- 35, PI 1 BPM @ 500,
did not comm to surr,
07/30- POH w/ pkr, WIH w/ 7" Arrow ret BP & ten pkr on 2-3/8 tbg, isolated 7" csg
31/83 leak 2523-3365, last BP setting @ 2490, press test 7" csg 2490 to surf 800/
15 min/ok, POH w/ BP & pkr
08/01/83 WIH w/ OE 2-3/8 tbg, POH LD same ND BOP, NU wellhead, rel DA&S WS Ut @ 3 pm
8/1/83, well SI, WO P&A approval.

RECEIVED
SEP 12 1983
O.C.D.
HOBBS OFFICE