| | \boldsymbol{g} | |
|--|--|--|
| DISTRIBUTION | | Form C-103 Supersedes Old |
| SANTA FE | NEW MEXICO OIL CONSERVATION COMMISSION | C-102 and C-103 Effective 1-1-65 |
| FILE | | 20000000 11-00 |
| U.S.G.S. | | 5a. Indicate Type of Lease |
| LAND OFFICE | | State X Fee |
| OPERATOR | | 5. State Oil & Gas Lease No. |
| SHINDD | Y NOTICES AND BEDODES OF THE | |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. (DO NOT USE THIS FORM FOR PROPOSALS | | |
| OIL GAS WELL OTHER-WIW | | 7. Unit Agreement Name |
| 2. Name of Operator | OTHER MIM | 0.5 |
| Mobil Oil Corporation 3. Address of Operator | | 8. Farm or Lease Name E. K. Queen Unit Tr. 10 |
| Three Greenway Plaza East, Suite 800, Houston, Texas 77046 | | 9. Well No. |
| 4. Location of Well | | <u> </u> |
| UNIT LETTER 0 660 FEET FROM THE South LINE AND FEET FROM | | 10. Field and Pool, or Wildcat E.K. Yates 7/Rivers Que |
| ł | · | |
| THE LINE, SECTION | 14 TOWNSHIP 18-S RANGE 33-E | имрм. () |
| | 15. Elevation (Show whether DF, RT, GR, etc.) | |
| | 1111 | 12. County Lea |
| 16. Check A | ppropriate Box To Indicate Nature of Nation P | |
| NOTICE OF IN | ppropriate Box To Indicate Nature of Notice, Report of | |
| | SUBSEQU | JENT REPORT OF: |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON REMEDIAL WORK | |
| TEMPORARILY ABANDON | COMMENCE DRILLING OPNS. | ALTERING CASING PLUG AND ABANDONMENT |
| PULL OR ALTER CASING | CHANGE PLANS CASING TEST AND CEMENT JOS | PLUG AND ABANDONMENT AA |
| | OTHER | |
| OTHER | | |
| 17. Describe Proposed or Completed Open | rations (Clearly state all pertinent details, and give pertinent dates, incli | |
| | | |
| 8/25/// 4340 TD, Queen jts 2-3/8 CL tbg, RIH w | 4256-4301. MI DA&S DD unit 4/22/77, instl 1 1/4-3/4 RB 5' L scraper to 4168. | BOP, rel pkr, POH, LD 137 |
| 4/26/77 4340 TD, Queen 4256-4300 w/75x Class H | 4256-4301. POH bit, ran $5\frac{1}{2}$ EZ-Drill set @ 4, max 1800 psi, spot 5x on EZ-Drill, circ m | 4165, Knox sqz Queen perfs |
| spot 25x plug to 2780, | spot 25x plug 1825-1605, POH, ran free pt cs | sg free @ 783. |
| 4/27/77 4340 TD, Queen | 4256-4301. Ran jet cutter, cut 5½ @ 760, H | ? & LD 24 jts 5½ 15.5# |
| J55, ran 2-3/8 tbt to 8 | 10, spot 35x Class H to 660. | , - |
| 4/28/77 4340 TD, Queen 4 hrs, tag plug @ 310, | 4256-4301. Tag plug @ 682, pull to 352, spo spot 35x plug 310-195, SDFN. | ot 35x plug to 237, WOC |
| 4/29/77 4340 TD, Queen weld on plate & marker, | 4256-4301. Tag plug @ 186, pulled 30', spot rel rig 3:30 PM 4/28/77. | : 10x plug 30' to surf, |
| FINAL REPORT. | | |
| ************************************** | | |
| 18. I hereby certify that the information ab | bove is true and complete to the best of my knowledge and belief. | |
| | | |
| SIGNED Kichard anders | | DATE 5-10-77 |
| PAN | OIL & GAG USERS | TOR |

DATE MAR 23 1970

CONDITIONS OF APPROVAL, IF ANY:

RIDENCES

MAY 13 1977

OIL CUNSERVATION COMM.
ROBBS, N. M.