

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. <u>E-744</u>	
7. Unit Agreement Name	
8. Farm or Lease Name <u>L.K. Queen Unit Tr. 8</u>	
9. Well No. <u>1</u>	
10. Field and Pool, or Wildcat <u>E-K Yates 7 River Queen</u>	
11. Elevation (Show whether DF, RT, GR, etc.) <u>3919.5 CR</u>	
12. County <u>Lea</u>	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

1. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

*Plug & abandon as per attached drilling summary*

I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNED <u>Christine O. Tucker</u>	TITLE <u>Production Clerk</u>
DATE <u>3-21-73</u>	
APPROVED BY <u>Leslie A. Clement</u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>
DATE	
CONDITIONS OF APPROVAL, IF ANY:	

DAILY DRILLING REPORT

E. K. QUEEN UNIT #8-1

E. K. QUEEN UNIT #8-1, E. K. Yates 7 Rivers Queen Fld, Lea Co, NM. OBJECTIVE: P&A.

3/7/73 4313 TD.

MIRU Bonanza csg pullers, tbg stuck in slips at surf, cut slip hanger off, work stuck prk 2 hrs, tbg came loose, rebound jarred pin out of elevators, dropped tbg in hole, SD for nite.

E. K. QUEEN UNIT #8-1, 4313 TD.

MI 2-3/8 work tbg, ran Bowen OS on one jt 2-3/8 tbg to 25', caught fish, P & rec 6 jts 2-3/8 CL tbg, rerun OS to 185, caught fish, worked prk up hole 9 jts, prk hanging up, worked prk down hole 2 jts, SD for nite.

E. K. QUEEN UNIT #8-1, 4313 TD.

Worked prk down to 4150, unable to work up hole, attempted to shoot tbg off @ 4145 three times and attempted to shoot off @ 4134 two times, SD for nite.

E. K. QUEEN UNIT #8-1, 4313 TD.

Ran 1-11/16 collar loc, stopped @ 1697, McCullough Tool Co ran 1-7/16 collar loc, then shot tbg @ 4075 & 4045, then cut tbg @ 4044 w/ chem cutter, P & LD 40 jts 2-3/8 CL tbg, SD for nite.

SD for week end.

E. K. QUEEN UNIT #8-1, 4313 TD.

Finish P & LD 2-3/8 CL tbg, ran 5½ csg scraper on 2-3/8 work tbg to 4058, POH, set 5½ CIBP on wire line @ 4056, dumped 2x of cmt on plug, top of cmt @ 4044, ran 2-3/8 tbg OE to 3900, SD for nite.

E. K. QUEEN UNIT #8-1, 4313 TD.

Load hole w/ mud, SD for high wind.

E. K. QUEEN UNIT #8-1, 4313 TD.

POH w/ 2-3/8 tbg, weld onto 5½ csg, pick up on csg, csg was parted, P & LD 20 jts 5½ csg, ran 2-3/8 tbg OE to 1700, SD for nite.

3/16/73 Spotted 20x Class H cmt @ 1650, calc top 1550, P & LD tbg to 680, then spotted 30x Class H cmt, calc top 543, finish LD tbg, inst'l dry hole marker and 10x Class H cmt plug @ surf, Rel Bonanza csg pullers @ 3:00 p.m. 3/15/73. Well P&A 3/15/73.  
FINAL REPORT.