UNITED STATES OF THE INTERIOR (Other Instruct

SUBMIT IN TRIPLICATÉ.

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

LC-067229-A

12. COUNTY OR PARISH 13. STATE

MM

Lea

GEOLOGICAL SURVEY							
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS		

	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRISS NAME
ī.	OIL GAS OTHER WIW	7. UNIT AGRESMENT NAMB
2.	NAME OF OPERATOR	S. FARM OR LEASE NAME
	Mobil Oil Corporation	E. K. Queen Unit TR.5
3.	ADDRESS OF OPERATOR	9. WELL NO.
	Three Greenway Plaza East - Suite 800 - Houston, TX 77046	2
4.	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)	10. FIELD AND POOL, OR WILDCAT
	At surface	E. K. Yates 7/River Queen
	660' FWL & 1980' FNL, Unit E. Section 14, T-18-S, R-33-E	11. SEC., T., R., M., OR BLK. AND SURVEY OR ARMA
_		Sec. 14, T-18-S, R-33-E
14	PERMIT NO. 15. ELEVATIONS (Show whether DE RT CR etc.)	19 COUNTY OF BURISH 12 POLOR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

3961

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

NOTICE OF INTENTION TO:			SUBSEQUENT EMPORT OF:			
[]						
TEST WATER SHUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF REPAIRING WE	LL		
FRACTURE TREAT	MULTIPLE COMPLETE		FRACTURE TREATMENT ALTERING CASI	ING		
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING ABANDONMENT	• x		
REPAIR WELL	CHANGE PLANS		(Other)			
(Other)			(Note: Report results of multiple completion on Completion or Recompletion Report and Log form	. WeII		

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
- 4-2-77 4356 TD, 4324 PBTD, Queen 4264 4309. MIRU DAS DDU.
- 4-4-77 Bled well down, install BOP, attempt to release pkr @ 4215, pkr stuck, back tbg off @ safety jt @ 4208, pull & laid down 138 jts CL tbg.
- 4-5-77 4356 TD, 4324 PBTD, Queen 4264-4309. Ran CS to 4210 POH, set cmt ret @ 4170 sq perfs 4264-4309 w/75 sxs H, SITP 1200, spot 5 sxs on ret, circ hole to 9.5# MLF.
- 4-6-77 4356 TD, 4324 PBTD, Queen 4264-4309. Ran tbg to 3300 spot 25 sxs H to 2850 POH, remove BOP's install jacks PU 4-2" center spear.
- 4-7-77 4356 TD, 4324 PBTD, Queen 4264-4309. Pull spear had wtr flow, PI 8-5/8 ann @ 1400 psi, 4½" csg fell in hole, caught csg w/OS FP est 3306 by stretch, ran cutter stopped @2832, cut 4½ @ 2793, worked scg to 190,000# pull, pulled into 739', SDN.
- 4-8-77 4356 TD, 4324 PBTD, Queen 4264-4309. Set FBRC @ 691, Howco sqx 160x H, displ to 991, SITP 900, SDFN.
- 4-9-77 Spot 15x 750-701, 10x 0-26, weld on plate, inst1 P&A marker, rel DA&S 4:30 pm 4-8-77, well P&A.

18. I hereby certify that the foregoing is true and correct					
SIGNED Kickard (Indison	TITLE _	Authorized	Agent	TED PATE	4-26-77
(This space for Federal or State office use)			DPRO	Arr	10
APPROVED BY	TITLE	\ P	L.	1079 - DAD	
CONDITIONS OF APPROVAL, IF ANY:			OCT 23	191014	>
*Se	e Instructi	ions on Revers	SING DISTR	ICT ENGINÉES	

RECEIVED

OCT 20 1875

O.C.D. HOBBS, OFFICE